



Secretaria de la companya della companya della companya de la companya della comp

STATE OF MICHIGAN ÉMMET CÖÜNTY RĔĆŎŘŎĔĎ

1995 DEC 18 PM 3:51

APR 2 9 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

					<i>y</i> .		
	EMMET	Located In:	Corner Code ≠	_<	Thenes.	A. Sipe OF DEEDS	
.—	(County)					W. Klype	
	•	PLEASAN	TVIEW TWP.		CEGISTER (OF DEED	
1.	Public Land Survey	T_36NR5W	E-7		_	" UEEUS	
		T R					
	ECRP #94	Τ R					
		T R		A 1.00.001 Ph.		: •• <u>-</u>	,
2.	Property Controlling	S T R		LIBER	А	PAGE 7	4
	in Section	S T R		•		<u>``</u> .	
3.	Miscellaneous	S T R		Dominton of Dogo			
	Property in Sec.	S		Register of Deed	is Stamp &	The Number	
		÷			*		
4.	Lot No, R	ecorded Plat		A R C	DEFG	3 H I J K L	
5.	Private Claims		·				Γ-
				2 - 6	5	- 3 - - 2 - - 1	-
				3	├─┼─┼		_
R	Richard E. Oelke	15 D	ecember 95	4 7 7	8-1-9-1	-10-11-1-1	2
i, _		in a field survey on	, 19	, 5			Ĺ
do	hereby certify that under require	uirements of P.A. 74, Michigan P.	A. of 1970, the corner points menti-	oned 6			
ın i	lines 1 and 2 above were in	conformance with regulations a	and rules therefore as required in	n the	(-15-14-1-1	3-
Ma	madement or by a decree of a	Court of I aw and/or that the core	artment of the Interior, Bureau of I ner points mentioned in lines 3, 4 a	Land			_
abo	ove were in conformance with	h the rules of the Michigan Board	of Land Surveyors or by a Decre	8 -19 -2	021	22232	4-
Co	urt of Law; established, re	e-established, monumented, re	-monumented, recovered, foun-	d as	┟╼╁╼╁╸		_
ext	pressed below:			ا ا ا ا م	9 28	-27262	5-
NC	OTE: Not more than 4 co	orners, all in the same town a	and range, may be recorded	11			
	on this certificate.			12 31 3		_31353	6-
				13			,
Α	Description of original m	nonument and accessories a	ad/or subsequent restoration:			· 	_

- E-7, Section corner common to sections 16,17,20,21, T36N, R5W
 - SEE REVERSE SIDE FOR HISTORY

APPROVED LAND CORNER P.A. 345 OF 1990 **Emmet County** 96 DEC.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - E-7, Section corner common to sections 16,17,20,21, T36N, R5W

Found 1-1/4" iron pipe, 3' long, in centerline of Stutsmanville Road. found previously set witnesses E. 70.53', 12" Maple, tagged W, 43.12', Power pole

(11) S35°Ė, (12) S42°W,

Maple, tagged 33983 NW face Power pole, tagged 33983 SE face Power pole, tagged 33983 NE face

43.12 , 58.72', (13) N36°W,

of Mic **OELKE** PROFESSIONAL SURVEYOR No. 33983

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - E-7. Section corner common to sections 16,17,20,21, T36N, R5W

At this point placed a 2" dia. 30" long PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program cap. This position is accepted as a careful and faithful perpetuation of the original corner.

> added new witness below 37.26', 3" Ironwood, tagged 33983 W face

Signed by REOave	Date 15 DECEMBER 1995
777007	
Surveyor's Michigan License No. 55103	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

CORNEL 24 94

36-5-E7 T36N R5W 16/17/20/21 STUTSMANVILLE AND HEDRICK ROADS

LIBER A PAGE 77

		•		
<u>Date</u>	Surveyor	Found	Witnesses	Notes
1840	GLO	16" Hemlo	ock	
1882	Schartzl	er Fd corner	ran E/L sec. 17 Pleasantview Highway Commissi	oner Book
1972	G. Young	1-1/4" ir	ron rod, from 10/72 copy MDOT 1) S38E 31.96' 18" twin elm 2) S75W 35.61' 20" elm 3) N35W 59.65' pp	field notes
1972	Green	Fd pipe, bound	ary survey L246/P496	
19??	ECRC	Fd pipe	4) NOOE 30.50' fence post 5) S75W 34.85' 18" elm 6) N28W 58.60' pp	
1973	Green	Symbol, Plat o	f Valley View Estates	
1973	Porter	Fd 1-1/4" rod,	LCRC Liber 1, page 96 4) N00E 30.50' fence post 2) S75W 35.61' 18" elm 3) N35W 59.65' pp	
1973	Porter	Fd 1-1/4" rod,	Boundary Survey Liber 243, pag 6A) S38E 69.67' 18 twin elm	je 281
1978	Bongiovan	ni Fd 1-1/2"	rod, LCRC Liber 1, page 297 7) S34E 6" maple	
			8) S40W 43.25' pp 3) N31W 58.63' pp	
1988	O'Neill	. 1	LCRC Liber 2, page 235 7) S58E 95.17' 5" maple(3009 0) S30E 70.60' 10" maple (300 8) S40W 43.25' pp (24586 W f 3) N31W 58.63' pp (24586 W f	95 E face)
			pp (24566 W I	ace;
1991	Oelke	Fd 1-1/2" rod,	Boundary Survey for Boynaire 11) S35E 70.57' 12" maple (3 12) S43W 43.12' pp (33983) 13) N34W 58.74' pp (33983)	3983)
1992	Ranger		14) S45E 70.10' 9" maple 15) S45W 42.84' pp 16) N30W 58.37' pp	