

LAND CORNER RECORDATION CERTIFICATE

96 DEC 31 PM 2: 21

| Filing Requirement of A | ct 74, Mich. P.A. 1970 | | | |
|--|--|--|--|--|
| EMALT | Code # 1 Dana & Sign | | | |
| Located In: Corner | REGISTER OF BEEDS | | | |
| 1. Public Land Survey T 37M R 4W G-13 | A.K.A | | | |
| ECRPHILL 136NA4W (7-1) | LIBER A | | | |
| TR | PAGE 143 | | | |
| 2. Property Controlling S T R | PAGE TTO | | | |
| in Section S T R | | | | |
| 3. Miscellaneous S T R Property in Sec. S T R | Register of Deeds Stamp & File Number | | | |
| | | | | |
| Lot No, Recorded Plat Private Claims | A B C D E E G H I J K L I | | | |
| · | 2 6 5 4 3 2 1 - | | | |
| | 3 | | | |
| 1. Themas D. Swence in a field survey on December 1 | 8 19 6 1 1 1 1 1 2 | | | |
| do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the coin lines 1 and 2 above were in conformance with regulations and rules theref | orner points mentioned | | | |
| current manual of survey instructions of the United States Department of the Ir | sterior, Bureau of Land 7 | | | |
| Management or by a decree of a Court of Law and/or that the corner points menti above were in conformance with the rules of the Michigan Board of Land Survey | oned in lines 3, 4 and 5 ors or by a Decree of a | | | |
| Court of Law; established, re-established, monumented, re-monumented, expressed below: | recovered, found as | | | |
| NOTE: Not more than 4 corners, all in the same town and range, ma | 20 20 20 21 20 21 23 | | | |
| on this certificate. | 12 31 32 33 34 35 36 | | | |
| A. Description of original monument and accessories and/or subsequ | rent restoration: | | | |
| • | | | | |
| Section Corner common to Section 33, and Section 34 T37N R4W | SURVEY & | | | |
| and Section 3, and Section 4, T36N R4W | REMONUMENTATION | | | |
| (SEE BACK OF PAGE FOR HISTORY) | · · - ia O tair is (MI 101) | | | |
| | MAY 0 5 1997 | | | |
| | COMMISSION | | | |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: | | | | |
| • | | | | |
| G-13, | 71 1 1 4 (0.0) | | | |
| Found 3/8" Pin, inside of 3/4" Pipe. Found 3/4" Pipe above 1-1/2" Cast Iron Pipe. Found 1-1/2" Cast Iron Pipe inside an extremely rotten cedar post. Very little remaining of cedar post, but | | | | |
| enough left to determine that pipe appears to have been set inside the cedar post. 1-1/2" Pipe APPROVED LAND CORNED | | | | |
| very much resembles pipes found at D-13, and E-13. | , P.A. 345 OF 1990 | | | |
| THIS CORNER IS ACCEPTED BY THE EMMET COUNTY REMO | NUMENTATION GROUP R.E. Ocus | | | |
| AS A FAITHFUL AND CAREFUL PERPETUATION OF THE ORIG | SINAL CORNER. 12 -30 -96 | | | |
| | | | | |
| | | | | |
| C. Description of monument for corner and accessories established to | perpetuate leasting the applifies of the appear | | | |
| • | perpetuate locating the position of the corner: | | | |
| G-13, Found 3/8" pin, inside 3/4" Pipe, which is above 1-1/2" Cast Iron Pipe, | which is | | | |
| inside an extremely old cedar stake, and replaced with a 2" diameter, 3 | O" long PVC | | | |
| Pipe with a Base magnet and a standard Brass Emmet County Remon Cap. Further set a monument box to preserve comer position. | SAS HOWARD IN A F S | | | |
| Witnesses: | SWENOR E | | | |
| (3) N51°W 54.84' - Southeast Corner Sidewalk (formerly McRae Lu | nber) No. | | | |
| (6) S56°W 37.54' - Power Pole (found spike nail) (7) N67°W 87.30' - Power Pole (found spike nail) | | | | |
| (8) S39°W 55.20' - 8" Jack Pine (found spike nail) | MAND LAND SURINI | | | |
| 11. T. S. 1 1991 | | | | |
| igned by Morrias O-Surrior | Date Of Confee 66, 1776 | | | |
| urveyor's Michigan License No. 12-26-16-5/28 | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 | | | |

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1911 REVISED MAY 14, 1975 REVISED JAN., 1983

PAGE 144

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 116 T37N R4W - G-13

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

| Date | Surveyor | | Vitnesses) | | |
|-------|----------------|---|------------|---|--|
| 1840 | GLO | Set Post Corner | (1) | Beech 6 - N38E 37 | |
| | | | (2) | Beech 6 N77W 11 | |
| 1892 | S.G.Main | Set Large Cedar Post 8" Dia., 3-1/2' Long | | | |
| 1893 | | | | | |
| | | surface. | | angles of 45°, N45°E | |
| | | | | N45°W, S45°E, S45°W | |
| | • | | | at outside Hwy. Limits. | |
| 1916 | S.G.Main | T-Rail 5-1/2' Long at above 1892 Position | | | |
| 1957 | E.C.R.C. | Found survey stake | (3) | 54.8' - S.E. Comer McRae Sidewalk | |
| | | • | (4) | S.E. 35.7' - Telephone Pole | |
| | | | (5) | 55.7 - East Corner McRae Vault | |
| 1963 | Schweigert | Found 3/4" Iron Pipe | | no witnesses | |
| 1,903 | & Young | round 3/4 Hour tpc | | TIO WILLCOSCO | |
| | J | | | | |
| 1969 | R.E.Bidstrup | Corner noted as found | | no witnesses | |
| 1969 | J.H.Green | Corner noted as found | | no witnesses | |
| 1505 | 1,5910,11.0 | Corner noted as found | | 110 Wildiesses | |
| 1969 | G.E.Young | Found 3/4" Pipe | | no witnesses | |
| .1050 | C P W | T 1 5/48 T | | | |
| 1972 | G.E.Young | Found 3/4" Pipe | | no witnesses | |
| 1973 | J.H.Green | Found 1/2" Re-rod | (4) | S.E. 35.7 - Telephone Pole | |
| | | | (3) | 54.8' - S.E. Corner McRae Sidewalk | |
| | | | | • | |
| 1979 | R.E.Bidstrup | Found Iron Pipe | (3) | 54.8' - S.E. Comer McRae Sidewalk | |
| 1919 | K.E.Didadap | Olina non ripo | (4) | S.E. 35.7 - Telephone Pole | |
| | | | (5) | 55.7' - East Corner McRae Vault | |
| | | | 2 av | ar aca minima bil | |
| 1983 | J.H.Green | Found Iron Pipe | (4) | S.E. 35.7' - Telephone Pole 54.8' - S.E. Corner McRae Sidewalk | |
| | | | (5) | 54.8 - 5.E. Comer Morae bidewark | |
| 1984 | J.B.O'Neill | Found 3/8" Pin in pvt. | | no witnesses | |
| | | | | an acar at the not | |
| 1992 | T.D.Swenor | Found 1/2" Re-rod | (4) | S.E. 35.7 - Telephone Pole 54.8' - S.E. Corner McRae Sidewalk | |
| | | | (3) | 34.8 - S.E. Comer Merae Briewalk | |
| 1992 | M.A.Trowbridge | Shows corner as found | •• | No witnesses. Survey rec. L.475, P.172 | |
| 1993 | Farrier | Found 1/4" Iron Pipe | (6) | S57°W 37.58' - Power Pole | |
| | Α, | at T-Intersection | (7) | N67°W 87.37' - Power Pole | |
| | | • | (8) | S40°W 55.22' - 7" Scotch Pine | |
| | | | (3) | N50°W 55.00' - S.E. Corner McRae Sidewalk | |
| | | | (9) | S75°E 131.91' - Power Pole | |
| 1995 | R.E.Oelke | Found 1/4" Iron Pipe @ McRae St | | | |
| | | | | | |