MAR 0 5 1998

MASTER 3685 PAGE

SECTION

1997 REMONUMENTATION PROGRAM

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970			COUNTY	i e e				
Genesee (County)	Located In:	Corner Code #	000	-	^ /	,			
1. Public Land Survey	T 6N R 7E	<u>C-5</u>		of Deeds St	Le d amp & Fi		mber	le _	_
2. Property Controlling in Section	STR STR STR	***************************************	1	a c D	E F G	н	r J	к	L
Miscellaneous Property in Sec.	S TR S TR		3	 	_	_ 3	2.		1_
4. Lot No , Red	corded Plat		5	8 -	b	_ 1. 0 _	_\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		12
I,Kevin B. Cleaver, ir	a field survey on <u>December 1</u> ,	19 97 do hereby state th	nat under	8 17	16	- 15-	1+	+	i 3-
in conformance with regulationstructions of the United State	igan P.A. of 1970, the corner points n ions and rules therefore as require es Department of the Interior, Bureau	mentioned in lines 1 and 2 abo ed in the current manual o J of Land Management or by:	ove were of survey		21	2 2 	2 3	 :	· 4
5. Private Claims I, Kevin B. Cleaver, ir requirements of P.A. 74, Mich in conformance with regulat instructions of the United State	n a field survey on <u>December 1</u> , igan P.A. of 1970, the corner points n ions and rules therefore as require	mentioned in lines 1 and 2 abo ed in the current manual o J of Land Management or by:	ove were of survey	8 17	16	- 15-	14		2

of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, reestablished, monumented, recovered, found as expressed below: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1823 GLO Set post and two (2) accessories Date ? GEI Found Iron Pin, three (3) accessories

Oct. 31, 1973 LCRC, Liber 1875, Page 592 Found 1/2" Hex Bar, four (4) accessories

Certified Survey, Liber 1872, Page 366 Found 1/2" Hex Bar, same four (4) accessories as LCRC, 1973 Oct. 31, 1973 GCRD

July 11, 1978 GEI May 2, 1989 GEI Found 1/2" Rod, five (5) accessories Survey for New Christian Fellowship Church

May 18, 1989 Found Iron Pin 2' Deep Raised, four (4) accessories

April 30, 1992 GCRD Certified Survey, Liber 2460, Page 481, Found 1/2" Iron, four (4) accessories

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Iron in Asphalt; October 31, 1973 LCRC, L 1875 P 592 - Found four (4) accessories; October 31, 1973 Certified survey, L 1872 P 366 - Found four (4) accessories and distance C-5 to D-5; July 11, 1978 GEI Records - Found Three (3) accessories; May 2, 1989 Survey - Found Distances C-5 to D-5 and angle C-5, D-5, D-4, May 18, 1989 GEI Records - Found three (3) accessories April 30, 1992 Certified survey, L 2460, P 481 - Found four (4) accessories;

The monument found was ratified by the Genesee County Peer Review Committee on December 4, 1997, as the accepted corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set the standard Bernsten monument SS-A-5-BR-30 with 3 1/2" brass cap stamped Genesee County Re-monumentation Corner 1997, #29242 over 1/2" Iron in Monument Box.

S 40° W, 52.50' - Set Re-mon. nail and tag over a GEI nail and tag in the East face of a 12" elm South, 38.10' - Set Re-mon. nail and tag over a nail and tag in the East face of a 15" elm S 50° E, 59.36′ - Set Re-mon, nail and tag over a nail and tag in the West face of a 12" aspen N 65° E, 94.72' - Set Re-mon. nail and tag in the South face of a 10" stem of a multi stem maple

Signed by (12/24/9 WESTLE CLEAVER PROFESSIONAL Kevin Banfield Cleaver, P.S., SURVEYOR Field Manager No 29242

0 F E S S 1 0

Surveyor's Michigan License No. 29242

97H-GCRM-LCRC-3582

88573

accordance with P.A., 345, 1996 VISED JAN., 1983 REVISED OCT., 1995 Co. Rep Date

Peer Group in

by

BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971