SURVEY & REMONUMENTATION

MAR 23 2000

Lot No.

Private Claim

1999 KEMONOMENTA FOR FROSKAM	<u> </u>
AND CORNER RECORDATION CERTIFICATE	. Pen Man
AND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	1 The live
11111174	144 3

or c	corners in	÷. ▲ f				au 100
	SECTION Genesee County)N	Located	f In: Davison	Corner Code # C-5	DEC 28 10 37 AM '99
1.	Public Land Survey		T 7N	R 8E	C-5	GENESEE COUNTY REGISTER OF DEEDS
			Τ	R		REGISTER OF DEEDS
		1.	Т	R	-	
			т	R		y 4358, P 735
2.	Property Controlling	s	т	R	**************************************	O(-100)
	in Section	s	т	R		
3.	Miscellaneous	s	т	R		
	Property in Section	s	т т	R		Register of Deeds Stamp & File Num

I, David J. Kenney, in a field survey on November, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were 5 in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

Recorded Plat

- Description of original monument and accessories and/or subsequent restoration:
 - 1822 G.L.O. Joseph Wampler D.S.
 - 1928 G.C.R.C. Stake, 1 accessory
 - 1974 L.C.R.C. L1898, P. 519 by Lyal H. Howison, P.S. #1840
 - Found nail and cap, 3 accessories
 - 1978 G.C.R.C. Irish Road - Found re-rod in monument box, 3 accessories
 - G.C.R.C. Irish Road Found 1/2" re-rod in monument box, 3 accessories 1983
 - 1990 L.C.R.C. L 2392, P. 159 by Grant J. Ward, R.L.S. #22445, 4 accessories
 - 1993 Survey L3410, P. 635 by James E. Kauas, R.L.S. #33138, 4 accessories
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" re-rod in monument box, and 1 accessory from 1928 G.C.R.C. Irish Road plans. Distance from C-5 to C-4 by stationing of 2,633.4 feet. 1978, 2 accessories (S60°E, 92.6 nail and tag in power pole, S45°W, accessories (S60°E, 92.6 nail and tag in power pole, S45°W, 72.30 nail and tag in power pole. 1983, 3 accessories (NE 81.44' top center of fire hydrant, SE 92.08' nail and cap in telephone pole, SW 71.77' nail and cap in power pole), 1987, 2 accessories (S40°E, 92.78 tag SE face of power pole, S55°E, 72.45 tag SW face of power pole). 1990 and 1993 some witnesses, 3 accessories (N50°W, 64.71' spk and disc #22445, NE face utility pole, S55°E, 92.75', nail and disc, S.W. face utility pole, S55°W, 72.43, nail and disc, SE face utility pole.

During my field work I measured between C-5 and C-4, 2632.53', 1928 G.C.R.C. 2633.4, 1993 survey 2632.76 and . between C-5 and D-5 2496.71', 1978 G.C.R.C. 2496.62 and 1993 survey 2496.79'.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

N45°E, 81.44 Top Center of Fire Hydrant S55°E, 92.84 Found Nail/disc Southwest Face Utility Pole S55°W, 72.75 Found Nail/disc Southeast Face Utility Pole N50°W, 64.71 Found Nail/disc #22445, Northeast Face Utility Pole

Ratified by Genesee County Peer Group November 24 1999. I set standard Bernstein monument (3 1/4" d. brass cap stamped "Gene County Remonumentation Corner, 1999" with 30" x 2 3/8" C stainless steel tube over 1/2" re-rod.

Surveyor's Michigan License No.



Date December 27, 1999

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYOR, JAN. 28, 18 REVISED MAY 14, 197 REVISED JAN., 198

Group Peer Ratified by in accordance with P 345, 1990

Co. Rep Date