MAY 3 1 2000

2564PAGE 546

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			Sm S &
Genesee	Located In:	Corner Code #	96 F 3 L
Public Land Survey	T 7n R 8E T R R	<u>M-1</u>	
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R		Register of Deeds Stamp & File Number Q^{ℓ}
4 f -4 81-	Demonded Diet		0,4 F
	Recorded Plat		ABCDEFGHIJKLM
I, Jack N. Owens do hereby certify that under in lines 1 and 2 above were current manual of survey ins Management or by a decree of above were in conformance of Court of Law; established expressed below:	e in conformance with regulations a tructions of the United States Depa of a Court of Law and/or that the cor with the rules of the Michigan Board f, re-established, monumented, re	vey on	6 18 17 16 15 14 13 5 7 10 10 20 21 22 23 24
NOTE: Not more than 4 on this certification	4 corners, all in the same town te.	n and range, may be recorded	11 31 32 33 34 35 36
A. Description of original	inal monument and accessorie	s and/or subsequent restoration:	13
1920, GCRC & WIT. BOO 1929/31, I.M.A. RECS, & DISTANCE TO COR. M	D.BINGHAM, PE-SURVEY OF I -3, NO ACCESSORIES.	STONE, IRON ROD & 4 NEW ACC	ESSORIES (COR. 8, DV,COR.36 RCH) NUMENTATION BUT SHOWS COR., SEC. LINE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994, FND SPIKE INSIDE 1 1/2" PIPE FLUSH & DRIVEN OVER 15" X 1/2 X 1" RECT. BAR (BASE 2' DOWN) ABOVE 18" X 3/8"

THREADED ROD AT 2.5' DOWN SURROUNDED BY REMNANTS BRICK & CROCKERY NEAR TOP & SMALL REMNANTS (OLD) OF WOOD, POSSIBLY A STAKE & 1 ACCESSORY FROM 1972 (NAIL W/FLG IN P/POLE TO NE 8 38.11')

SEE COR. M-2, LCRC & CERT. SURVEY (ACT 132) OF SURVEY OF E. LINE SEC. 1 FOR DISTANCES (L.2561, P.62-65). ALSO, DISTANCE ALONG E. LINE SEC. 36, T8N, R8E, ARE CLOSE TO GLO - 2640 (40.00 CHS) [CP= 2645.3' [40.080 CH] IN 1937 GCRC & 2644.50' [40.068 CH] IN 1972 FSE)

T CONCLUDE THE CORNER POSTTION DOESN'T SEEM TO HAVE CHANGED SINCE 1920 & PROBABLY MUCH EARLIER SINCE THE STONE RECOVERED IN 1920 INDICATES LONG HISTORY OF CAREFUL PERPETUATION BY CO. SUR. &

THE IRON ROD BY THE GCRC SEEMS TO BE THE BOTTOM ONE WITH ERN OF PERPETUATION. THE STAKE REMNANTS MAY POSSIBLY BE A PATTERN OF PERPETUATION. THE STAKE REMNANTS MAY POSSIBLY BE PARTS OF THE GLO STAKE AS THEY WERE IN FRAGILE CONDITION. THE DISTANCES N. OF THE COR. ARE NEARLY THE SAME AS THE GLO RECORD. I ACCEPT THE 1 1/2" PIPE OVER THE BAR & ROD AS A FAITHFUL & CAREFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

RATIFIED BY GEN. CO. PEER GROUP NOV 9, 1994.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: I REPLACED THE RECOVERED MONUMENTATION & SET THE STANDARD

1920 & 5 NEW ACCESSORIES (COR. 76 RCH)
1972, CERT. SURV. (L.1838, P.476 & 477) S.R. BROWN, PS 17613; NO MON. DESCRIBED, 3 NEW ACCESSORIES
1992, ROWE ENG. SURV. RECS. - FND 1 1/2" PIPE, NO ACCESSORIES

Accessories:

N45E, 38.11' - FND NAIL W/FLAGGING IN S
FACE OF POWER POLE

& 37.92' - FND PK W/FLAGGING IN SW FACE

& 38.28' - SET GC REMON TAG & PK IN SE FACE

S55E, 49.11' OF 18" PINE 49.11' - SET GC REMON TAG & NAIL IN NE FACE

850W, 59.35' - SET GC REMON TAG & NAIL IN NW FACE OF 12" OAK N75W, 69.25' - SET GC REMON TAG & NAIL IN SW FACE COUNTY REMONUMENTATION CORNER 20709, 1994" WITH 30" X 2 3/8" O.D. STAINLESS TEEL TUBE) 8" BELOW GRADE. Ratified by Peer Group in accordance with P.A. 345, 1990

BERNSTEN MONUMENT SS-A-5-BR-30 (3 1/4" D. BRASS CAP STAMPED "GENESEE

OF MICHIE JACK N. **OWENS** LAND SURVEYOR No. 20709 LAND SUR

Signed by & Surveyor's Michigan License No. 20709

OF 12" BOX ELDER

Date Dec 301794

KOVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1983



