18AY 2 A 1997

James Bally Stranger

Signed by Secrifican License No. 29242

THE CALL STATE

1996 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

		Filing Requir	ement of Act 74, Mich.	P.A. 1970	; ;		35
	r corners in			ì	16.4	_	<u>)</u>
Ge	nesee	Located In:	Corner Code =##	(A)		ن دوا د	;;;
	(County)			α		<u></u>	, i
1	Public Land Survey	T 8N R 6E	M-5	\ \tag{1}		E	<u></u>
••	,	T R		(1)	Lee N	بغ	(* ·
		T R	·	90	,	ω,	
		T R		'	Semantic and the Control of the	ri i i em em zancznoś się s	ا بربي
2.	Property Controlling	S T R	4		माम्हर ह	EPHOOND	4, 41
	in Section	> S T R					
3.	Miscellaneous	\$ T R		Reg	ister of Deeds S	tamp & File Nu	umber
	Property in Sec.	S R		1			
		D Dial					
4.	Lot No	Recorded Plat			ABCD	F G H I	J K
5.	Private Claims				2 - 5 5	_ 4 3	- \$
			•		3	_	++
					⋄ ├_	_ 9 10 _	_\\
ı K	Cevin B. Cleaver	P. Shea field survey on Nove	ember 22 19	92	5		_
do	hereby certify that under re	equirements of P.A. 74, Michigan P.A	., of 1970, the corner points me:	ทแอกยอ	6 _ 10 _ 17 _		-14
in	lines 1 and 2 above were	in conformance with regulations a	nd rules therefore as required	d in the	7 1	Ĭ	1
CUI	rrent manual of survey ins	tructions of the United States Depa of a Court of Law and/or that the corn	riment of the interior, Bureau : er noints mentioned in lines 3	or Land 4 and 5		21 22	23
Ma	magement or by a decree o	with the rules of the Michigan Board	of Land Surveyors or by a Dec	ree of a	9 19 20	21 22	
Co	urt of Law; established,	re-established, monumented, re-	monumented, recovered, fo	und as			
ex	pressed below:	•			10 30 29	-2827	-26 -
NC	OTE: Not more than 4	corners, all in the same town a	nd range, may be recorde	d	'' - - - 		
	on this certificate	e.			12 - 31 - 32-	_3'33'4	-3'5
		_			13		Ш.
A.		I monument and accessories ar		on:			
	1821, GLO	Set post with two					
	July 16, 1916	Recorded plat of	"Long-Acres"				
	July 11, 1916	Recorded plat of	'Nutana Homes"				
	Aug. 20, 1920	Recorded plat of '					
	March 1, 1968	MSHD construction	plans				
	1970	Gould Engineering	, Inc. records, fou	ind 5/8"	rod in monu	ment box	
		with four (4) acce	essories				
		•					
₿.	Description of corner	evidence found and/or method	applied in restoring or ree	stablishing	corner:		
	Found 5/8# roc	i in monument box and	Four (4) accessorie	s from 1	1970 records	. We then	
	tied into the	recorded plats of "Loi	ng-Acres". "Nutana	Homes" a	and "Stanley	Park"	
	tica into the	recovered practice.	,		•		
	The monument f	ound was ratified by t	the Genesee County	Peer Rev	view Committe	ee on	
	November 13, 1	1996 as the accepted co	orner.				
	,	·		Ratified	by Peer	Group in	
				accordan	ice with P.A.	345, 1990	
				į.	/\ \ \	~ -0	
			,	Co. Rep.		N. V. F.)
		•	•	Date	11-13%	N/P	
		3					
					•	•	
_				loopiina the	s position of the	· · · · · · · · · · · · · · · · · · ·	:
C .	Description of monum	ent for corner and accessories	established to perpetuate	rocating the	e position of the t	Joiner.	
	Set the standa	ard Bernsten monument S	SS-A-5-BR-30 with 3	31" brass	cap stampe	. .	
	Genesee County	remonumentation corne	er 1996. #29242. o	ver the	5/8" rod in	monument b	ох
		•		1			
	S 42° E 61	[.97' Set memon tag	j in northeast face	of powe	er pole		
		3.00' Set remon tag	in southeast face	e of powe	er pole		
	N 49° W 468	3.68' Set remon tag	g in southwest face	of powe	er pole		
		3.79 Set remon tag	in Secutionast face	of powe	er.pole		•
	· ,	:	E OF MICHAEL				
	•		4				
		_ {	KEVIN RANGE				
	_/.	n. 1.1/1/1 1:	BANFIELD CLEAVER		مصدر است		
Sic	ned by Second	Bankill (Well)	SURVEYOR DAIL	LIOY Z	Z, 1994	?	
٠	Kevin Banf	ield Cleaver, P.S.,	Fiera Manager	•			

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26 REVISED MAY 14 REVISED JAN