1907 8 9 1907

Surveyor's Michigan License No.

1996 Remonumentation Program LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	48,50	1-11-12-61-631	Filing R	equirement of A	Act 74, Mich. I	P.A. 1970					,	> C #
For cor	ners in	, .					MASTE	R 3	43	4 PAG	E &	294
	_Genes	see	Located In:	Corner Code	#			4	H .			
1. Pub	lic Land	d Survey	T 8N R 8E T R T R	D-5			·			nec 73	\$150.8 F	re cono
2. Propin S 3. Miso	perty Co ection cellaned perty in	ontrolling S S ous S Sec. S	T R T R T R T R T R T R T R T R T R T R			Regis	ter of E		s Stan	ムジ		niber)
4. Lot	No	, Recor	ded Plat			 	<u>^</u>	в с	D E	FG	ні	JK
5. Priv	ate Cla	ims					2	ļ	- 5-		_ 3	
do here mention required Bureau mention Land S	eby certined in lite of the control	ify that under requines I and 2 above surrent manual of side Management or nes 3, 4 and 5 abos or by a Decree	in a field sur pirements of P.A. To were in conformations of by a decree of a love were in conform of a Court of Lav disas expressed belowere	74, Michigan P.A. ance with regulati of the United Slates Court of Law an nance with the rule w; established, re-	of 1970, the common and rules to Department of the codes of the Michigan and the codes of the Michigan and the codes of the Michigan and the M	orner point: therefore a: the Interior orner point: an Board o	5 5 — 1 5 7 — 1	8	-1720	-18	-10	-11
NOTE:		nore than 4 c ded on this cert	ornėrs, all in ti lificate.	he same town	and range,	may be	10	 	-2 ¹ 9	-2'8	-2 ¹ 7	26
A. Des	cription	of original monu	iment and access	ories and/or sub	sequent restor	ration:	13			Ï		
D-5	1987 -	Beech Rowe Engineer West 37.50' Na Nail/Tag#11192 Iron leaning NV	Post WIT: S20'\ ing, Survey (L.22 iil/Tag#11192 S.F 2 NE Face 6" Silv V. i45.94' G.L.O. 18	292, P.297 & L.20 Face 24" R.Oak; ver Maple; S80°E	302, P.963 & t North 24.62' N E 9.50' Nail/Tag	3412, P.6 Vail/Tag#1 g#11192 N	1192 V INE Fa	V.Fad ace 6	e 6" \ " Oak;	V.Oak;	N45	W 28.96
Distanc	es:		45.94 G.L.O. 18 45.94 G.L.O. 18	•								
В.	Descri	iption of corner e	vidence found an	id/or method app	lied in restorin	g or reesta	blishi	ng co	rner:			
D-5		West 37.58' Fn North 24.58' Fn N45*W 28.95' Fn S80*E 9.58' Fn North 1.43' Fnd	Rod w/ Cap#2070 d Nail/Tag#11193 d Nail/Tag#1119 Fnd Nail/Tag#1110 d Nail/Tag#11193 I T-Iron leaning N te running East-W	2 S.Face 24" R.0 2 W.Face 6" W.0 192 NE Face 6" 9 2 NNE Face 6" 0 IW	Oak Silver Maple	6	Ratifie accord Co. R Date	ep	e wit	T		oup In 6, 1990 <u>Jan</u>
The mo	numen	it found was ratif	ied by the Peer R	Review Committe	e on October	30, 1996,	as the	acce	pted o	orner.		
C.	Descri	iption of monume	ent for corner and	l accessories est	ablished to per	rpetuate lo	cating	the p	ositio	n of the	e corn	er:
D-5		West 37.62' Se N05°E 24.67' S N45°W 28.92' S S08°E 5.45' Se S70°E 9.28' Se North 1.44' Fno North 1.5' Feno	with Brass General to 60d Nail/Genesset 60d Nail/Genesset 60d Nail/Genesset 60d Nail/Genesset 60d Nail/Genesset T-Iron leaning Ner running North	ee Co. Tag S.Fa esee Co. Tag E.F esee Co. Tag NE ee Co. Tag E.Fa ee Co. Tag SW	ace 24" R.Oak Face 8" Oak E Face Twin 6' ace 10" Poplar	" Maple	cation			JAI KOV	MICA VIES VAS ND VEYOR	
0:	\	m 50	ex non		Data	Decem	her 20	100	议			UR.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971