mas 0 \$ 2000	
SECTION LAND CORNER RECORDATION CER Filing Requirement of Act 74, Mich. F	RTIFICATE Register's Uffice ss.
For corners in	Received for record the
ONTONAGON Located In: Corner Code #	day of November
(County) GOGEBIC	A B 19 90 14 19 17 11
1. Public Land Survey T <u>48N R 41W</u> B - 13	A. D. 1999 at 19:25 o'clock
$\frac{140NR41W}{47NR41W} = \frac{13}{8-13}$	
1R	Liber 7 Of CORMES
TR	00 page 269
2. Property Controlling S T R	Bamona Collins, Deputy
in Section ST_R	Register of Deads
Property in Sec. S T R	
	Register of Deeds Stamp & File Number
A bookhing to the same	-
4. Lot No, Recorded Plat 5. Private Claims	
	A B C D E F G H I J K L M
1 Corner common to Sections 6 & 31, T47-48N, R41W.	2 - 6 - 5 - 4 - 7 - 3 2 1 - 1
(Farl W Applekamp)	3
I, Earl W. Applekamp, in a field survey on Sept. 29,/19 99 do hereby state that requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above w	under 4 7 8 9 10 11 12
- contouriestor with regulations and fules incretore as required in the current manual of current instructions	. at the
Times States Department of the interior. Bureau of I and Management or by a decree of a Caust of Law	
Board of Land Surveyors or by a Decree of a Court of Law established to established	ntinen 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 36 35
	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	
Original Corner established by William A. Burt, U.S. Depu Surveyor in 1847. Set Cedar Post.	ty
ORIGINAL BEARING TREES:	
12" Cedar N30°E 5 Links (3.30 feet)	A DEED AD ONE THE
	MARK MECULA APPROVED
20" Hemlock N62°W 15 Links (9.90 feet)	Sail W applekant
B. Description of corner evidence found and/or method applied in restoring or reestablishin	SOUNDS ENDOUGHINGS
No original evidence was found. I found a 4"X4" metal ye	llow tag 18 feet North
of the position I set the corner. The tag was scribed 4	feet South to approximate
corner. I re-established the corner by single proportions	ate measure and on the
Town line between the monumented SW Corner of Section 31,	and the St Corner of
Section 32. These two corners had been monumented from or 1961 and 1970 respectively.	riginal bearing trees in
Research on file with the Ontonagon County Remonumentation	n Program Representative.
Description of monument for corner and accessories established to perpetuate locating the	na manillan afat
•	
At the corner position I set a $2\frac{1}{2}$ "X30" split base aluminum	pipe with a 3" OF Mo.
cap stamped to read: County Remonumentation, T47N, T48N,	R41W, 1, S6, 111/4 ATE
At the corner position I set a $2\frac{1}{2}$ "X30" split base aluminum cap stamped to read: County Remonumentation, T47N, T48N, S31, 1999, P.S. 17610. I established 3 bearing trees and Nail in 7" Maple N01°E 20.53' - Nail in 7" Maple S Nail in 7" Maple Due East 46.55' - 6' Steel Sign Post	a reference object * * EARL W.
Nail in 7" Maple NO1°F 20 53! Not1 to 7" was	APPLEKAMP APPLEKAMP
Nail in 7" Maple Due East 46.55' - 6' Steel Sign Post	27°E 18.40' F PROFESSIONAL 2
	NO. NO.
	17610 . Set s
	POFFECINAL WITH
igned by Earl W applekanys	No. 17610 No. 17610 September 29 1999
igned by / Carlo Capacitation	Sentember 20 1000

17610

Surveyor's Michigan License No.