MAR 02 2000

,
SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	CHON		•	
For corners in				
GOGEBIC (County)	Located in	v :	Corner Code #	Sog.1
1. Public Land Surv	ey 7 1 1	r <u>47</u> NR <u>41W</u> r R r R r R	E-1	
Property Controll in Section Miscellaneous Property in Sec.	ing S 1 S 3 S 5	TR TR TR		

ineguater's (iffice) Engebic County ss.

Received for record the 22 MD day of OctoBER A. D. 1999 at 11: 20 o'clockm., and recorded in of CORNERS 7 page 256 Colims Deput Kamaa

Register of Deeds Stamp & File Number

Register of Deeds

LiotNo	, Recorded Plat
5. Private Claims	

Section Corner common to Sections 32 & 33, T48N R41W & Sections 4 & 5, T47N R41W.

I. Earl W. Applekamp, in a field survey on Sept. 14, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented. Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

CORRECTION: SEE LIBER 7, PAGE 272

5 6 8

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by William A. Burt, U.S. Deputy Surveyor, June 1851. Set Cedar Post.

ORIGINAL BEARING TREES:

14" Hemlock 14" Hemlock N35°E N65°W 2.64 feet

11.88 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original bearing trees were found. The only original evidence found was a leave swamp call on the original field notes, which state, going West on bottom of Section 33; leave swamp 79.00 chains. Corner was set at 80.00 chains. Corner was re-established by single proportionate measure and on line between opposite Section Corners on the Township line. This location is in agreement with the swamp call indicated above.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

At the corner position I set a $2\frac{1}{2}$ "X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, 47N R41W, S32, S33, S4, S5, 1999, P.S. 17610. I established three bearing trees and a Steel Sign Post.

Nail in 7" Maple Nail in 10" Maple N59°W M30°E

24.91' - Nail in 5" Maple S05°W 53.20' 40.30' - 6' Steel Sign Post South 0.73'

EARL W.
APPLEKAMP
PROFESSIONAL
SURVEYOR
NO.
17610 SURVEYOR
NO.
17610
OFESSIONAL TRANSPORTED TO THE PROPERTY OF T

Signed by Lail	W Coplet	amp	
			17610
Surveyor's Michigan Lice	nse No		

Date	September	17,	1999