

DEG 1 5 1998

## LAND CORNER RECORDATION CERTIFICATE

Register's Office 33.

SECTION For corners in	Filing Requi	rement of Act 74, Mich. P.A.	Received for record the
Gogebic (County)	Located In:	Corner Code ##	17 th day of SEPTEMBER
1. Public Land Survey	T <u>48N</u> R <u>45W</u> T R T R	G-10	A. D. 1998 at 1:15 o'clock  P. m., and recorded in  Liber 7 of CORNERS  page 60
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous</li></ul>	S T R S T R S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		register of Deeds Stamp & File Number
5. Private Claims	; T.48 N., R.45 W		2 6 5 4 3 2 1 2
do hereby certify that under requirement in lines 1 and 2 above were in current manual of survey instructions and address of a cabove were in conformance with	irements of P.A. 74, Michigan P.A. conformance with regulations a ctions of the United States Depa Court of Law and/or that the corn the rules of the Michigan Board	nust 27, , 19 98 A of 1970, the corner points mention of rules therefore as required in the triment of the Interior, Bureau of Laner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found	ed 6 18 17 16 15 14 13 nd 7 15 15 14 13 nd 7 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 cor on this certificate.	rners, all in the same town a	and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original m	onument and accessories ar	nd/or subsequent restoration:	13

Corner established by Austin Burt on 9/22/1848. Original B.T.s --- 14" Y. Birch S.25 $\frac{1}{2}$  W. 17 links (11.22') --- 16" Hemlock N.18 E. 21 links (13.86')

Road plans of County Road #519, approved Feb. 1946, indicate this corner as being 45' (scaled) west of station 158 + 80.7 and an 18" culvert as being at station 157 + 75. Local reports by residents indicate that the road has undergone major reconstruction since 1946.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner position found marked by a  $1\frac{1}{2}$ " iron pipe at the intersection of very old fence lines south and west. Pipe lays 42.2 feet west of station 158 + 80.7. The culvert at station 157 + 75 appears to have been reset since 1946, to station 157 + 71.7, a distance south of 3.3 feet.

All original B.T.s have been destroyed by road construction . long local usage and its' conformity to the original notes, I have accepted its' location as being the same as established by Austin Burt in 1848.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a  $3\frac{1}{4}$ " stamped aluminum cap and the following new B.T.s:

10"	White Pine	s.56 w.	15.86
9۳	Aspen	N.12 E.	4.83
5"	Balsam	S.26 E.	13.41'
61	Steel sign rail	s.77 W.	2.10'

**RICHARD** L. DRAHN LAND SURVEYOR No. 21564 LAND

Date <u>August 29, 1998</u>

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.

REVISED MAY 14, 1975 REVISED JAN., 1983