

CONS. 4047  
7/58

✓

**MICHIGAN**  
**DEPARTMENT OF CONSERVATION**  
**FORESTRY DIVISION**

**LAND CORNER RECORD**

T. 51. NR. 35 W. . .

. . . . . Houghton . . . . . COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 15 - 22 . . . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . . .

WITNESSES TO CORNER 3-25-58 . . . . .

8" hemlock N 45°, E 41 links. Marked "S. 15 T" . . . . .

10" cedar S 8°, W 67 links. Marked "S. 15 T" . . . . .

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR**

**RESTORED.** Replaced from two original B. T.'s. Hard maple bearing N 50°, W 20 links and soft maple S 42°, E 15 links. Both trees green and in fair condition. Found iron pipe in place. Corner found by I. Stevens, District Forester.

**SURVEYORS SEAL**

*Billy D. Buckler*  
SIGNED Billy D. Buckler . . . . . DATE 5-1-59 . . . . .  
REGISTERED LAND SURVEYOR