LAND CORNER RECORDATION CERTIFICATE

For	corners in	Filing Requirement of Act 74, Mich. P.A. 1970											
	Houghton (County)	Located In:	Corner Code ##										
1.	Public Land Survey	T <u>52H</u> R <u>36M</u> T <u>52H</u> R <u>36M</u> T R	87 A6										
	Property Controlling in Section	S T R S T R											
	Miscellaneous	S T R											
_	Property in Sec.	S T R		Regi	ster c	of De	eds:	Stam) & F	ile N	umb	æг 	_
4.	Lot No	, Recorded Plat										٠.	
5.	Private Claims				Ĥ	ŤÌ		Ť	Ť	Ĥή	Ť	ᡝ᠊ᢆ	一
					2	ķ─┦	\$	╁╌╅╌	╬	<u> </u>	- \$ -	┿	i
					3	₩	+	₩		↤	+	┿	 —
		A6 Octob	er 12, 1995		4	}	_ ¼_	ֈ	+-։՝	·—	_11_	ֈ_,	2
		, in a field survey on <u>87 Octob</u>			5	\sqcup		↓ _↓	┵	\vdash	丄	1_	乚
		requirements of P.A. 74, Michigan P.A. o			4	⇊	_	 - -	,	<u>, </u>	_ _1#_		 3—
		 In conformance with regulations and structions of the United States Departs 			7L	Ĺ		LĬ	Ш	Ш.	_ Ï	1	Ĺ
		of a Court of Law and/or that the corner			Γ	רו	Ţ		\prod	\Box	Ţ	\Box	[_
		with the rules of the Michigan Board of			<u>.</u> [iΠ	-20 		1 -2	í	-23 	1 -2	•
	rl of Law; established ressed below:	, re-established, monumented, re-m	onumented, recovered, found			П	$\neg \vdash$	П	77	\Box	\top	1	
•		corners all in the same town an			⁰├─₃	╚┼	29 I	26-	十ºî	<u>/</u>	-2'6	┼	5-
41) I	ir' Noi more fran 4	COTRACE SILIP TRA CAMA TOWN SN	n renge meu he recorded	1	11					/			4

A. Description of original monument and accessories and/or subsequent restoration;

on this certificate.

- (87) Quarter corner common to Sections 18-19. Corner established in 1846 by Hiram Higgins: "40.20 Set 1/4 Sec. post. Sugar 10 N75E 17, do 10 S40M 13. 1966 Mead records show: "1 1/2" iron pipe, Yellow tag on 9" Hard Maple (Beaver) N09E 12', 6" Ash (Beaver) S66M 9', 8" Basswood(Beaver) S41E 20'".
- (A6) Quarter corner common to Section 1B T52N-R36M and Section 13 T52N-R37M. Established in 1845 by Nm A. Burt: "40.00 Set of Section post. Hemlock 12 S27M 37, do 16 N30M 28". Head records dated Jan 24, 1966 state: 4" Ash post at corner Old Hemlock stump (B.T.) N26M 17 ft., B" Hard Maple (Beaver) S24M 9 ft". Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (87) Original post and accessories not recovered. Found a 1 1/2 iron pipe marking the corner in accord with the 1966 Mead hard maple witness to the ME. Distance East to monumented Section corner is 0.74 ch. longer than record. Distance west to Section corner on Range line is 1.37 ch. shorter than record and I observed a 3 deg. 42 min. right deflection in the section line at this corner. I accepted the pipe as the best available evidence of the position of the original corner.
- (A6) Original post not recovered. Mead's Ash post was not recovered. Remonumented the corner at record bearing and distance from the remains of the original bearing trees. The Hemlock NN was recovered as a rotted stump of proper size and species. No markings were found. A distinct stump hole marks the location of the other Hemlock BT. The corner is also in accord with Mead's 8" Maple, recovered as described. Also, An old unreadable location poster, possibly by Copper Range, faces the corner on a 14" Sugar. A dead 4" squared Sugar was found adjacent. Distances North and South to adjacent Section corners are -0.06 ch. and +0.32 ch. respectively, compared to the original record. At the position for the corner, I placed a 1"I.D.x36" iron pipe capped with a 4" dia. cast aluminum MONR tablet, appropriately stamped.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

 (87) Found 1. 1/2° iron pice.

 (84) Set 1° pine with 4° MNN cap.

(87) Found 1 1/2" iron pipe. (A6) Set 1" pipe with 4" MDNR cap. Blazed and scribed the following new Blazed and scribed the following new bearing trees: bearing trees: 5" Sugar N75E 10.9 "1/45 NBT" 14" Sugar NOSW 26.6" "1/45 MBT" "1/45 N8T" 6" Maple S25E 15.1' 15" Maple N47E 10.1' "1/45 MBT" found with blazes and a beaver. 10" Sugar \$20E 3.7" "1/45 NBT" 10" Ash S68W 10.B' "1/4S NBT" 8" Sugar NBON 17.6" "1/45 MBT" found with blazes. Bearings are magnetic. Placed a 3" 12" Maple N16E 12.4" "1/45 MBT" with squared ash post adjacent. blazes and location poster. Bearings are magnetic.

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Signed by Stephen J. Syspenhalo:

10-26-95

Surveyor's Michigan License No. ______339