OCT 2 9 1996

For corners in

REMONUMENTATION Re-Mandille, Page 16

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Huron Located In: Corner Code #	
T_R_	T-13 STATE OF MICHIGAN HURDN COUNTY RECORDED
T R	10 SEP 96 8:41 A.M.
in Section S T R	FRANCES L. HOLDWICK REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L
	2 6 5 4 3 2 1 1
I, <u>Charles S. Getz</u> , in a field survey on <u>July 2</u> , 19 <u>96</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lin conformance with regulations and rules therefore as required in the current manual of United States Department of the Interior, Bureau of Land Management or by a decret that the corner points mentioned in lines 3, 4 and 5 above were in conformance with Board of Land Surveyors or by a Decree of a Court of Law; established, re-errecovered, found as expressed below:	les 1 and 2 above were in f survey instructions of the e of a Court of Law and /or 6 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same town and range, may be re on this certificate.	10 30 29 28 27 26 25
· ·	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
Description of original monument and accessories and/or subsequent I-13 GLO Notes	restoration:
Set Post at 80.00 Chains Sugar 20", N75°W, 11 Links	County Surveyor's Record - Large Rock just .55 North of Ford Axle, Act 74 - None, Act 132 - None
Hemlock 7", N13°W, 91 Links	County Surveyor's Record - 3/4" Iron Pin 1.0 North of Large Stone, Act 74 - None, Act 132 - None, Unrecorded Survey dated 5-23-9
Description of corner evidence found and/or method applied in restoril	by Case Surveying or reestablishing corner:
I-13 SW Cor, Section 35, T15N-R14E Found Monument Box in Asphalt Road (Interse of Huron Line Road and Parisville Road)	APPROVED PEER BOARD MEETING CLB Sept 7, 1996
J-13 S 1/4 Cor, Sec 35, T15N-R14E Found Railroad Spike, 6" Deep, in Gravel Road Bed (Huron Line Road)	
	•
 Description of monument for corner and accessories established to per I-13 	petuate locating the position of the corner: J-13
SW Cor, Section 35, T15N-R14E Mounment Box in Asphalt Road West 20.46' to Mounment Box 550°W 52.75' to Road Sign 645°E 42.92' to Concrete Project Marker 145°W 56.40' to Concrete Project Marker 145°W 56.40' to S 1/4 Cor, Sec 34, T15N-R14E 12st 2642.46' to S 1/4 Cor, Sec 35, T15N-R14E	S 1/4 Cor, Section 35, T15N-R14E Railroad Spike in Gravel Road Bed North 53.65' to Nail in E. Side of Power Pole N30°W 40.90' to West End of 24" C.M.P. North 198.83' to Nail in E. Side of 24" Ash West 2642.46' to SW Cor, Sec 35, T15N-R14E East 2610.50' to SE Cor, Sec 35, T15N-R14E
igned by Charles S. Met milliming of Mich.	Date July 15, 1996
Surveyor's Michigan License No. 25843	
Charles S. Getz Land Surveyor Form Approved by Michigan State Board of Professional Surveyors, Jan. 28, 1971 No. 25843 Revised May 14,1975	