*Common to A13 - Sand Beach Twp T16N-R15E Common to A01 - Sherman Twp T15N-R15E *Common to M01 - Paris Twp T15N-R14E	B
SURVEY & REMONUMENTATION JAN 2 2 1998 For corners in SURVEY & Re Mo 1997 REMONUMENTATION LAND CORNER RECORDATION CERTIFILING Requirement of Act 74, Mich. P.A.	Milicate 1. 1970
HuroSECTION Located In: Corner Code #	
1. Public Land Survey Sige1 T16N R14E M-13 V T15N R14E M-13 V T16N R14E A-13 T15N R15E A-13	STATE OF MICHIGAN HURON COUNTY RECORDED
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	26 NOV 97 8:58 A.M. FRANCES L. HOLDWICK REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKIM
I, <u>Charles S. Getz</u> , in a field survey on <u>Aug. 17</u> , 19 <u>97</u> do hereby state that unce requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of tunited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumenter recovered, found as expressed below:	in he 5 / 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration: M-13 1834 G.L.O., H. Parke D.S. Post Pine 18", S84°W, 8 Links B. Ash 16", N81½°E, 21 Links Co. Surveyor Records - NON: Records - Iron Recorded Surveys - NONE Huron Surveying 10-25-76 L.C.R.C. 1994 Remonumentations	on Rod
B. Description of corner evidence found and/or method applied in restoring or reestablishing c M-13 SE Cor, Section 36, T16N-R14E Found 3/4" Re-Rod in Monument Box Accepted as the best available evidence of original corner position (Intersection of Helena & Finkel Roads)	corner:
C. Description of monument for corner and accessories established to perpetuate locating the p M-13 SE Cor, Section 36, T16N-R14E Found 3/4" Re-Rod in Monument Box N45°W 71.35' to Spike in Power Pole S45°W 66.66' to Spike in Power Pole S45°E 64.50' to Spike in Tele Box Post N30°E 89.22' to PK Nail in W. side of Power Pole South 2693.94' to W 1/4 Cor, Sec 6, T15N-R15E East 2479.79' to S 1/4 Cor, Sec 31, T16N-R15E	Charles 8. Getz Land Surveyor No. 25845
	vember 20, 1997
TEER GROUP APPROVED AT TEETING LOU. 25, 1997 RUB. FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14,1975	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995