1998 REMONUMENTATION

The - Man Jules / Page 184

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74 111 Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

For Corners in					RECORDED		
Huron (County)		Located in:		Corner Code #	11 DEC 98 9:42 A.M.		
1. Pi	Public Land survey McKinley T 17 N R 10 E				FRANCES L. HOLDWICK REGISTER OF DEEDS		
in	operty Controlling Section scellaneous	s s	_T R T R		Register of Deeds Stamp & File Number		
I, Jan do here in lines current Manage above v Court o	nes T. Meek by certify that under re 1 and 2 above were in manual of survey instrument or by a decree of vere in conformance wiff Law; established, re	, in a field su quirements of P. conformance wit uctions of the Un f a Court of Law ith the rules of th	rvey on _October 3 A. 74, Michigan P.A. of h regulations and rules ited States Department and/or that the corner pre e Michigan Board of Lar	1970, the corner points mentione thereof as required in the of the Interior, Bureau of Land pints mentioned in lines 3, 4 and 3 and Surveyors or by a Decree of a ented, recovered, found as	2 6 5 4 3 2 1 1 12 3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7		
expessed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					10 30 29 28 27 26 25 11 12 31 32 33 34 35 36		

Original Survey South Bdy. T17NR10E, 1835, Harvey Parke, D.S. J-13 South & Corner of Section 35

Post

Hemlock 20", N81°E, 24½ links Hemlock 11", N28½°W, 10 links

County surveyors record; iron pin Recorded surveys: L3, P61; L4, P763

LCRC: none

Corner of Sections 35 and 36 Post Elm 22", N47°E, 31 links Beech 8", N32°W, 10 links

County surveyors record; none

Recorded surveys: L1, P266; L4, P763

LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of original monument and accessories and/or subsequent restoration:

J~13 South 4 Corner of Section 35 K-13 Corner of Sections 35 and 36

There is no remaining evidence of the original corner position &

REMONIMENTATION

Found 1" pipe in mon box At intersection of Berne & Sturm Rds.

Accepted as the best available evidence of the original corner position.

JAN 2 8 1999

SECTION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13 South 역 Corner of Section 35

Corner of Sections 35 and 36

At proportionate distance

Set '3" iron w/cap #39089 in mon box

From which:

رط igned⊒

Tag on power pole bears N56°E, 66.4'

Tag on power pole bears N60°W, 63.8'

Tag on power pole bears \$50°W, 67.9'

½" iron in mon box bears East, 35.5'

1" pipe in mon box

From which:

Tag on power pole bears N40°E, 62.15' Road sign post bears \$55°E, 64.55' East leg of direction sign bears South,

33.14

MINISTER MINISTER Tag on power pole bears N48°W, MILE OF MICH

MEEK

MANUS LAND SHAN

Date Dece

≣urve∖or's Mich/gan License No. <u>39089</u> PPROVED AT PEER BOARD MEETING, 11-24-98