## ACCEPTED BY THE HILLSDALE COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT MEETING HELD ON LACE OF 1990 AT MEETING HELD ON LACE OF 1990 AT MICHIGENBERG, CO. REP.

## LIBER 3 PAGE 40

97381

RECORDED HILLSDALE GO. MICH.

## REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

'94 NOV 28 AM 11 07

For c	orners in						_							
	Hillsdale		Located In:	Corner Code ##				Just	lu.	C	)a,	~ <del>3</del> c	ኒፖርጎ	سا لاس
	(County)						•	RI	Ğ			0	• • •	w.
4 5	ula la and Company		T 6S R 2W	E-13				RI	.G. (	)F I	DEE	DS		
1. P	ublic Land Survey		T R		SURVI	ΞY ,	ર.							
			T R	#\F-C				<b>/*</b> & 6						
			T R	REN		=141	<i>6</i>	UN						
2 P	roperty Controlling	S	T R											
	Section		T R		APR 27	199	9							
• • • • • • • • • • • • • • • • • • • •	liscellaneous		T R			ster		eds S	Stam	n &	File	Nur	her	r
Р	roperty in Sec.	s	T R		COMM					<b>~</b>				
	, -						~							
4. L	ot No, , !	Recorde	d Plat			Α	в	D 0	E F	G	н	ı j	ĸ	L M
5. P	rivate Claims					٦٦	П			П	$\top$	$\prod$	Т	
						<u> </u>	f	— 5— 	Τí	十	-3— 	† î	1	-1-
						3	1 1	_	† †	_		<del>     </del>	十	-
E	adomials I Cutobon		Mas	combor 17	Ω <i>4</i>	4	7-1	8 	<del> </del> ∳	+	-10-	11	<u>'</u>	-12
I Fr	ederick J. Cutcher	, in a fi	eld survey onNO	<u>/ember 17                                   </u>	olionod	5 ├	+		╂╌╂	+	+-	+	十	$\dashv$
do nei	reby certify that under re	quiremen n confort	nts of P.A. 74, Michigan P.A mance with regulations a	i. of 1970, the corner points me nd rules therelore as required	ntionea d in the	6	18	-17	1/6	-	-15	┿╌╬	1	3
currer	nt manual of survey instr	ructions o	of the United States Depa	rtment of the Interior, Bureau	of Land	7	+-1	$\dashv$	+	$\perp$	+-	++	$\dashv$	+
				er points mentioned in lines 3,		8	19	20	<del>  2</del> 1	-	-22	2	3	—2 <b>4</b> —
above	were in conformance w	ith the rul	les of the Michigan Board ished monumented re-	of Land Surveyors or by a Dec monumented, recovered, fo	oree of a und las	9	┵┩		+			$\downarrow \rightarrow$	-	_
	ssed below:	re-establi	ished, monumented, re-	-monumented, resovered, re	and do	10	30-	l 29	2E	,	_27—	26	<u>.</u>	25
NOTE	: Not more than 4 o	corners.	all in the same town a	ind range, may be recorde	ed	11	$\bot$				—	1		<del></del> -
	on this certificate					12	31	32	33	,	_34	3,	5——	36
						13	$\bot$					$\perp \perp$	$\bot$	
A. C	escription of original	monume	ent and accessories ar	nd/or subsequent restoration	on:									

Survey #934, Oct. 5, 1882, George Mark, Co. Surveyor: Stone (no witnesses)

Robert E. Burris, Sr., LCRC Liber 1, Page 485, June 9, 1975: Found stone for N.E. corner of Sec. 5, T7S, R2W and set corner 89.10' West.

GLO = 135 links West of E-1, T7S, R2W

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 60D spike over Harrison marker and brick, 89.1' West of E-1, T7S, R2W. Replaced with 3/4"x36" County remonumentation rod and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4"x36" County remonumentation bar 89.1' West of E-1, T7S, R2W

Top center telephone stanchion, N. 25° W., 45.33' N.E. corner barn, S. 65° W., 62.78'

Nail in W. side 12" Pine, S. 5° E., 80.40'

Bottom N.W. corner concrete post, East 113.15'



Signed by Ireduciff.	Cutcher
Surveyor's Michigan License No.	24592