· 8 402		
WE'NTA' LANI	O CORNER RECORDATION CERTIFICA	ATE (ICT 3 16 PM '94
For corners in SUNNEY and Filling	g Requirement of Act 74, Mich. P.A. 19	970 TEN OF DEEDS
INGHAM NOW O'S Checated In:	Corner Code ##	Danie Or anson
For corners in SURVER TO 1995 Filling INGHAM White Oak Townshim 5 1. Public Land Survey T	2E B-5	THEHAM COUNTY, MICH.
T	7	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		A B C D E F G H I J K L !
t. R. W. Steadman, in a field survey on do hereby certify that under requirements of P.A. 74, Min lines 1 and 2 above were in conformance with reg current manual of survey instructions of the United St Management or by a decree of a Court of Law and/or the above were in conformance with the rules of the Michig Court of Law; established, re-established, monumexpressed below:	chigan P.A. of 1970, the corner points mentioned ulations and rules therefore as required in the ates Department of the Interior, Bureau of Land at the corner points mentioned in lines 3, 4 and 5 gan Board of Land Surveyors or by a Decree of a ented, re-monumented, recovered, found as	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the sam on this certificate.	ne town and range, may be recorded	11 12 31 32 33 34 35 36
2). 12-28-1839: Volume 1,	Joseph Wampler, U. S. De 19 links and 12" Sugar S7 Page 152, County Surveyor riginal bearing trees as	2°W 8 links. Anson Jackson used this
B. Description of corner evidence found and/o Found 1/2" iron pipe and c in good condition but cap Ingham County Remonumentat	ap in monument box in cer was unreadable. Replaced	iter of Iosco Road; pipe wa I the pipe with standard
		RICHARD W. STEADMAN LAND SURVEYOR NO. 11370 AND SUR
C. Description of monument for corner and accessed 3/4" smooth iron rod a and took the following wit	ind cap stamped "P. A. 34!	5, PS 11370" in monument bo
Found nail and tag 11370 in Set nail and tag 11370 in	W. side 22" Maple NO4°W No. side 12" Hickory S47°N S. side triple 8" Elm NS S. side twin 10" Elm N81	27.37 feet # 33.63 feet 6°W 59.58 feet °E 88.93 feet
Signed by Richard W. Stand	Oman Date Sep	tember 9, 1994
Surveyor's Michigan License No.	P.A. 345 INGHAM COUNTY PEER APPROVED _9/14/94 MC	M APPROYED BY MICHIGAN STATE BOARD OF LAND SUBYEYORS, JAN. 28, 19 REVISED MAY 14, 19 REVISED JAN., 19

B-5, T2N, R2E

Part A - Continued

- 3). 4-26-76: Land Corner Recordation Certificate (Rec. 1-06-79, L5-P145), R. W. Steadman L.P.S. 11370 "dug hole in Iosco Road but found nothing; location falls in road cut area. Re-established corner in center of road opposite fence lines North and South. Set 1/2" iron pipe and monument bosto mark the corner. Witnesses: 8" Hickory S47°W 34.09 feet, 20" Oak S62°1 61.90 feet, 18 Maple NO8°W 27.55 feet".
- 4). 6-02-76: Certified Survey Map (Rec. 6-10-76, L2-P725), R. W. Steadman calls for the monument and witnesses given in 3). above.
- 5). 10-18-1988: Private Records of D. L. Clifford L.P.S. 25837 surveying for the subsequently cancelled Supercollider Project surveyed Section 18, T2N, R2E, and established coordinates for the corners. Computation of distances from his coordinates indicates that it is 2668.61 feet East, 2671.00 feet South, and 2148.24 feet West to the adjacent corners.