4. Lot No.

expressed below:

Private Claims _

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

Oct 24 8 43 AH '95

For corners in		· ming re-	quirentent of Act 74, mions	REGISTER OF DEEDS
-INGHAI ALAIEI	7— _(County) DON TOWNSHIP	Located In:	Corner Code =++	THEHAM COUNTY, MICH.
1. Publi	ic Land Survey	T _3N R _1W T R T R T R		
	erty Controlling	S T R S T R		
•	ellaneous erty in Sec.	S R S T R		Register of Deeds Stamp & File Number

DAVID R. LOHR , in a field survey on 5/25/94 & 9/15/95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

__ , Recorded Plat ____

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11
- A. Description of original monument and accessories and/or subsequent restoration:
 - 1-11: 1. POST SET BY MUSGROVE EVANS IN DECEMBER 1826, WITNESSED BY:
 - B. ASH 10" NORTH 47 DEGREES WEST 3 LINKS (1.98')
 - B. ASH 5" NORTH 40 DEGREES EAST 16 LINKS (10.56')
 - 2. A.P. DRAKE IN AN 1877 SURVEY RECORDED IN VOLUME 4, PAGE 57, STATES "FOUND OLD WITNESS STUMPS AND TOOK NEW BEARINGS". VIS. REECH 2D" NORTH 61 1/2 DEGREES WEST, 52 1/2 LINKS (34.65') NO MENTION OF MONUMENT.

CONTINUED ON BACK

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - I-11: VISITED LOCATION AND FOUND 1/2" IRON AS PER LCRC OF L. 4, PG. 237, ON C/L HARPER RD. AND 7.5 FT. WEST C/L WOLVERINE RD. ALSO FOUND 1/2" IRON IN MON. BOX 8 FT. EAST X 10 FT. SOUTH. DETERMINED THAT THIS IRON WAS TRAVERSE POINT #5044 SET IN 1978 BY INGHAM COUNTY REMON. SQUAD. MON. BOX WAS INSTALLED BY INGHAM COUNTY RD. COMM. OVER THIS POINT. EXCAVATED 4'x 4' AREA TO A DEPTH OF 3.0' CENTERED AROUND WILLIAMS IRON AND FOUND NOTHING. LOCATED 1/8 CORNER SOUTH OF THIS LOCATION (MISC. #7), BROUGHT IT TO THE SURFACE, AND EXTENDED THE SECTION LINE NORTH AND DOUBLED THE MEASURED DISTANCE FROM MISC. #7 TO THIS NEW POSITION MATCHES CLOSELY THE WITNESS OF ITEMS #5-8 TO THE 3" OAK, N 86°E, 113.85 FT. RETURNED ON 9/15/95 AND EXCAVATED AN AREA 2.5 FT. E&W BY 7.0 FT N&S STARTING ON THE WILLIAMS EAST-WEST SECTION LINE AND LYING NORTH. CONTINUED ON BACK
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11	1: SET 3/4" X 24" STANDARD REMON. B	BAR /	PA 345 CAP	#30090 IN
	MON BOX. OVER TOP OF STONE/POTTE	RY:	WITNES	SES BY:
	FD. N&T 18998 S/S 48" OAK,	AZ.	83 DEG.	114.20'
	TRAV. PT. #5044	AZ.	178 DEG.	14.25'
	FD. N&T 18998 W/S 10" CHERRY,	AZ.	168 DEG.	77.13'
	FD. N&T 25828 N/S P. POLE,	AZ.	235 DEG.	59.72
	SET N&T #30090 W/S P. POLE	AZ.	349 DEG.	35.87'
	BEARING AND DISTANCE TO H-11	AZ.	270-20-39	2738.581
	BEARING AND DISTANCE TO J-11	AZ.	90-01-34	2614.03'
	BEARING AND DISTANCE TO MISC #7	AZ.	181-10-23	1326.82'
	WILLIAMS 1/2" IRON	AZ.	241-03-00	9.30'
Signed by _	Haved R. John		Date	10-3-9

OF MICHIG DAVID R. LOHR ROFESSIONA SURVEYOR No.30090 POFESSION

<u> 30090</u> Surveyor's Michigan License No. _

P.A. 345 INGHAM COUNTY REVISED MAY 14, 191 PEER APPROVED 9/26/95 MC

REVISED JAN. 191

I-11 CONTINUED

- 3. MISC. FIELD NOTES DATED 1/12/1877, SURVEYOR UNKNOWN, "SAYERS RD. SURVEY" NO MENTION OF MONUMENT. WITNESSED BY:
 BEECH 20" N 61 1/2 DEG. W, 52 1/2 LKS (34.65')
- 4. SURVEY BY A.P. DRAKE 1878, FOLDER 1, PG. 65. NO MENTION OF MONUMENT, "NEW" WITNESSED BY: BEECH 20" N 61 1/2 DEG. W, 59 1/2 LKS (39.27')
- 5. W.A. ROWE, COUNTY SURVEYOR, IN A SURVEY DATED 3/31/1896, RECORDED IN FOLDER 1, PAGE 64, STATES: "STONE BLUE 2 X 5 X 27 IN. LONG" "O.P.F. & O. GOVT W. T. WITNESSED BY:

 ELM 8" SOUTH 77 1/2 DEGREES EAST, 109 1/2 LINKS (72.27')
 S. OAK 3" NORTH 86 DEGREES EAST, 172 1/2 LINKS (113.85')
- 6. W.A. ROWE, COUNTY SURVEYOR, IN A SURVEY DATED 3/31/1896, RECORDED IN VOL 2, PAGE 249, STATES: "FOUND OLD POST FROM FORMER SURVEYS" "O.P.F. BLUE STONE 2 1/2 FEET SET" WITNESSED BY:

 ELM 8" SOUTH 77 1/2 DEGREES EAST, 109 1/2 LINKS (72.27')
 S. OAK 3" NORTH 86 DEGREES EAST, 172 1/2 LINKS (113.85')

 SHOWS DISTANCE SOUTH TO I-12 OF 40.125 CH. (2648.25')
 SHOWS DISTANCE WEST TO H-11 OF 41.46 CH. (2736.36')
- 7. W.A. ROWE, COUNTY SURVEYOR, IN A SURVEY DATED 4/14/1896, RECORDED IN VOL 2, PAGE 250, SAME WITNESSES AS ITEM 6, BUT NOW SHOWS DISTANCE WEST TO H-11 OF 41.40 CH. (2732.40')
- 8. E.A. CALKINS, AUG. 1904, MISC. FIELD NOTES, BK.5, PG 140,
 "FOUND CORNER AT NW COR. SEC. 35." WITNESSED BY"

 S.OAK 6" NORTH 81 3/4 DEGREES WEST, 172 LINKS (113.52')
 ELM 10" SOUTH 77 DEGREES EAST, 109 LINKS (71.94')
 "NOTE: BEARINGS RECORDED BY W.A.ROWE 1896 COULD NOT BE MADE TO CHECK,
 SO I TOOK NEW BEARINGS ON SAME TREES."
- 9. NO OTHER REFERENCES FOUND IN COUNTY SURVEYORS RECORDS
- 10. RECORDED SURVEY BY AUSTIN C. WILLIAMS DATED 7/11/78, LIBER 3, PG.423. NO MENTION OF MONUMENT, WITNESSED BY:

 NAIL AND TAG IN 18" OAK NORTH 15 DEGREES EAST, 35.90'

 NAIL AND TAG IN 12" CHERRY SOUTH 25 DEGREES EAST, 74.80'

 NAIL AND TAG IN 44" OAK NORTH 86 DEGREES EAST, 122.73'
- 11. L.C.R.C. BY AUSTIN C. WILLIAMS DATED 6/11/78, LIBER 4, PG.237, "SET 1/2" IRON BAR WITH IDENTIFICATION CAP BY PROPORTIONATE MEASUREMENT EAST AND WEST IN CLOSE ACCORD WITH GLO RECORDS."
 WITNESSES SAME AS ABOVE IN TIEM #10.
- 12. UNRECORDED SURVEY BY PETER BEAVER, LLS #25828, DATED 7/30/91, JOB NUMBER 91020-01, STATES " TWO CORNERS WERE OBSERVED...USED WILLIAMS CORNER...BECAUSE IT WAS RECORDED."
- 13. UNRECORDED SURVEY NUMBER A-4263, BY RON LESTER, PS #18998, DATED 5/2/94, REFERS TO WILLIAMS 1/2" BAR AND CAP. LIBER 4, PAGE 237. WITNESSED BY:
 NORTHEAST CORNER GARAGE FOUNDATION, 221° AZ., 126.35'
 BEAVER NAIL AND TAG IN NW SIDE UTILITY POLE, 237° AZ. 50.42'
 SET GALV. NAIL AND 1 1/4" TAG, LS#18998 W/S 12"CHERRY, 164°AZ., 74.62'
 SET GALV. NAIL AND 1 1/4" TAG, LS#18998 S/S 48"OAK, 85°AZ., 122.77'
 BAR/CAP (OLD REMON TEMP.PT#5044) IN MON. BOX 141°AZ., 12.70'
- 14. NO OTHER REFERENCES FOUND.

I-11; PART B- CONTINUED:

EXCAVATED DOWN TO TOPSOIL AT DEPTH OF 20". FOUND 2" X 5" X 27" VERTICAL STONE SURROUNDED BY SHARDS OF BROKEN POTTERY IN NORTHWEST CORNER OF NEW EXCAVATION AT DEPTH OF 10". ACCEPTED THE STONE AS THAT OF ITEMS 5-8. LEFT STONE IN PLACE. SET 3/4" X 24" STANDARD REMON. BAR/PA345 CAP #30090 ALONG WEST SIDE OF STONE WITH TOP OF BAR OVER TOP OF STONE. SET MON BOX. OVER BAR AND STONE AND POTTERY. CORNER FALLS 4.5 FT. NORTH OF C/L HARPER RD. & ON C/L WOLVERINE ROADS. STONE IS 4.55 FT. NORTH X 8.11 FT. EAST OF LOCATION OF WILLIAMS IRON. REMOVED MON. BOX FROM WILLIAMS IRON AND PATCHED HOLE. LEFT MON BOX IN PLACE OVER TRAV.PT.5044.

2807