DEC 1 4 1993

CON	ANA	ISSI	ON
	A 1 F R 2 I	~~~	10-614

LAND CORNER RECORDATION CERTIFICATE DEC 2 12 18 PM 193 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	t mild tredam	cilicity of Mor 1-4, miles at 1 at 1	REGISTER OF DEEDS	
•			Paris Donner	
INGHAM	Located In:	Corner Code ##		
••			INGHAM COURTY- HICH.	
DELHI TOWNSHIP 1. Public Land Survey	T _3N R _2W T R T R T R			
Property Controlling in Section	S T R S T R		•	
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number	
Property in Sec.	S T R			
4. Lot No, Re	corded Plat		A B C D E F G H I J K L	1
5. Private Claims				_
			2 - 6 - 5 - 1 - 1 - 3 - 1 - 2 - 1	_
	•		3	_
do hereby certify that under require lines 1 and 2 above were in courrent manual of survey instruct Management or by a decree of a Cabove were in conformance with Court of Law; established, reexpressed below:	irements of P.A. 74, Michigan P.A. oconformance with regulations and tions of the United States Departs Court of Law and/or that the corner the rules of the Michigan Board of established, monumented, re-m	cober 30 , 1993 of 1970, the corner points mentioned if rules therefore as required in the ment of the interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a conumented, recovered, found as	4 7 8 9 10 11 12 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25	
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town and	d range, may be recorded	12 31 32 33 34 35 36	
A. Description of original mo 1. Original Post Tam 8 N87E 10 Swp Oak 5 S49		/or subsequent restoration: Evans in Dec. 1826.	- - - 計	
2. A marginal no	te in Ingham Coun	ty Register of Deed	s copy of the GLO	

notes:

S. Oak 20 N77W 98 New Elm 14 N511E 471

B. Description of corner evidence found and/or method applied in restoring.or reestablishing corner: Searched apparent area of corner and found P.K. nail just west of M.H. on centerline Holt and Aurelius Road. Tied to what I believe is original monumentation in Plats of Holt Farms No. 1 and Phillips Subdivision. These measurements show corner should be 1.00'East of found P.K. which would make corner fall on South rim of manhole. P.K. as recorded by Parish falls 3 West of found P.K. Assumed found P.K. and P.K. as recorded by Parrish are not the corner location as recorded by Clyde Stephens in 1972. Assumed Clyde Stephens corner

location on South edge of manhole was the same as I established at

this time. Cut "X" in South rim of M.H.

Field work conducted by Dave Clifford P.S.#25837

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Cut "X" in South rim of Manhole centerline Holt and Aurelius roads.

Az 131° 59.09' Az 222° 60.21' Centerline walk signal post Centerline traffic light support post Az 326° 70.23' Centerline Fire Hydrant Set Nail & Tag #25837 in N.W. side util. pole Az 43° Found "PK" nail Az 270° Found "PK" nail 1.001

Maria LAND

November 29, 1993

Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

SURTINOR

- 3. R. J. Robb, County Surveyor, used corner in a survey in Dec. 1906 recorded in Vol. 5 page 46 as a stone.
- 4. Corner is called for in Plat of Holt Farms #1 as recorded in Liber 7 of Plats page 13 by J. A. Dinsmore P.E. in 1921 and Phillips Subdivision as recorded in Liber 9 of Plats page 4 by J. A. Dinsmore P.E. in 1925. Both plats are immediately adjacent to corner.
- 5. Ingham County Road Commission Grid Map. P.K. Nail (1964)
 P.P. N.E. 56.28'
 P.P. E.N.E. 59.06'
 P.P. S. E. 55.84'
- 6. Clyde Stephens LS #3829 recorded corner in Nov. 1972 in Liber 1 of corners page 569 as a found P.K. nail in centerline of two section line roads. P.K. nail is on the South edge of a manhole. Survey tag & nail in three utility poles N27°44'E 56.62'
 N66°53'E 59.25';
 S64°48'E 56.35'
- 7. Trevor Parish LS# 24609 recorded corner in Oct. 1978 in Liber 5 of corners page 30 as a found P.K. nail with the same witnesses as in item #6 and a distance of 2748.00' to J-7.
- 8. George Young LS #17640 used corner in a survey in July 1986 recorded in Liber 5 of surveys page 43 with the same monument and witnesses as in item #6.
- 9. Maurice Mahieu #28414 used corner in a survey in Jan. 1989 recorded in Liber 5 of survey page 1085 with the same monument and witnesses as in item #6.
- 10. Ronnie Lester LS#18998 used corner in a survey in Sep. 1990 recorded in Liber 6 of Surveys page 484 as a found P.K. nail. Centerline of walk signal post N.W. 60.84 SW. Corner concrete pad for transformer N.E. 63.64' Centerline walk signal post S.E. 59.90' N. E. corner concrete base of walk signal post S.W. 58.33' and a distance of 2745.06! to J-7