DEC 1 7 1998

accincol

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

liher

9 Page

438

For corners in						
INGHAM COUNTY	Located In:	Corner Code #	÷	FIL	ED	
Meridian Township				980061		
1. Public Land Survey	T <u>4N</u> R <u>1W</u> TR TR	E-1		12/01/1998 REGISTER C Paula Jo INGHAM CC	F DEEDS hnson	
2. Property Controlling S in Section S	T R T R T R		•			
3. Miscellaneous S Property in Sec. S	T R T R		Registo	r of Deeds St	amp & File	Number
4. Lot No, Recorded 5. Private Claims			а в с	5 E F 6	н г ј	KLI
I, <u>Larry A. Bryan</u> , in a field so requirements of P.A. 74, Michigan P.A.	. of 1970, the corner points	mentioned in lines 1 and 2 abov	re ,	5-4-	32	
were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of				- B 9	101	112
Law; established, re-established, monu	mented, recovered, found as	s expressed below:	of 5 18	1716	151	413
NOTE: Not more than 2 corners, all on this certificate.	in the same town and range	e, may be recorded	8 19	_2021_	222	324
A. Description of original monum	ent and accessories and	or subsequent restoration:	10 30	29 28	272	625-

2). 07-15-1847: Record of Surveys, Vol. 2, Page 13, County Surveyor Anson Jackson notes the U. S. witnesses: "Aspin 6 S12-1/2W 31 lks., do. 5 S53E 11 lks."

1). 02-04-1827: U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "At 79.10 chains, intersected North boundary 37 links East of post, corner of Sections 32 & 33, T5N, R1W and set post, corner to Sections 4

& 5 from which: Aspen 6 in. S11W 31 lks., Aspen 5" S53E 11 lks."

- 3). 05-09-1848: Record of Surveys, Vol. 2, Page 65, County Surveyor Anson Jackson again notes the U. S. witnesses: "Aspin 6 in. S W 31 lks., do. 5 S53E 11 lks."
- 4). 12-23-1974: Land Corner Recordation Certificate for E-13, T5N, R1W (Rec. 2-27-75, L1-P907, Clinton County Records), M. F. Fouty, P.S. 18989, states "Found 3/4" pipe at the base of an old anchor post at intersection of old fencelines North, East and West. Records of eight area surveyors disclosed no additional evidence; tag and nail South side 16" tree ENE 2.55', tag and nail South side 6" tree WSW 5.02', tag and nail East side 8" Oak South 27.20'."

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron bar and cap #18989 in good condition at Northeast base of 14" Ash with fence remnants running East and West as called for in Item 5 above, other witnesses gone. Accepted bar and cap as the best evidence of the location of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1/2" iron bar and cap #18989 in place as found to mark the corner and took the following witnesses:

Found 3/4" iron pipe (E-13, T5N, R1W) West 24.52 feet (Rec. 37 lks. = 24.42') Set nail and tag #25832 in North side 16" Ash S80°E 13.79 feet Set nail and tag #25832 in East side 16" Ash N30°W 15.12 feet Set nail and tag #25832 in East side 18" Hickory North 53.45 feet



Signed by July 2	Date November 16, 1998
Surveyor's Michigan License No. 25832	

E-1, T4N, R1W

Part A - Continued

5). 12-23-1974: Land Corner Recordation Certificate (Rec. 2-27-75, L3-P345), M. F. Fouty, P.S. 18989, states "Set 1/2" bar and cap on Township line at intersection of old fences South, East and West in close accord with original government measure. Records of eight area surveyors disclosed no additional evidence; tag and nail North side 14" tree ESE 13.70', tag and nail East side 14" tree NNW 15.60', tag and nail East side 14" tree South 0.95'."

· SUBSIDIATE CONTROL

- 6). 01-09-1975: Certified Survey Map (Rec. 02-27-75, L2-P312), M. F. Fouty, notes the same monument and witnesses as Item 4 above. He shows E-1, T4N, R1W East of E-13, T5N, R1W, but does not give the distance between them. He also gives a distance of 2662.38 feet from E-1 to D-1.
- 7). 03-14-1983: Certified Survey Map (Rec. 08-09-83, L4-P743), J. A. Porter, P.S. 19003 shows this corner, but gives no monument description nor witnesses. He shows E-1, T4N, R1W East of E-13, T5N, R1W, and gives 24.42 feet (37 lks.) as the distance between them. He also gives distances of 2713.46 feet from E-1 to F-1, and 2580.96 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet).
- 8). 01-25-1988: Whitehills Woods, Liber 42 of Plats, Page 45, J. A. Porter notes "NE Corner, Section 5, T4N, R1W, Meridian Twp., Ingham Co., Mich." He also gives distances of 2661.25 feet from E-1 to D-1, and 2582.98 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet).
- 9). 06-28-1988: Whitehills Lakes Subdivision No. 4, Liber 43 of Plats, Page 27, J. A. Porter notes "NE Corner, Section 5, T4N, R1W, Meridian Twp., Ingham Co., Mich." He also gives a distance of 2661.24 feet from E-1 to D-1.
- 10). 02-02-1990: Whitehills Woods No. 2, Liber 45 of Plats, Page 37, J. A. Porter notes "NW Corner, Section 4, T4N, R1W, Meridian Twp., Ingham Co., MI., Liber 3, Pg. 345". He also gives distances of 2661.25 feet from E-1 to D-1, 2582.98 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet), and 2639.39 feet from E-1 to F-13, T5N, R1W.

DEC 1 7 1993

CECTON

RECORDED
ABOVEDON
ABO