LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	COTRACE	i.

ro	Iron	Located In:	Corner Code ##	
-	(County)	Eddards III.	0011167 00016 447	
1.	Public Land Survey	T 41N P32N	K1	
		T R	L1	
		T R		
		T R		
2.	Property Controlling	\$ t T R		
	In Section	S T R		
3.	Miscellaneous	STR		

Register of Deeds Stamp & File Number

4. Lot No. __ _ . Recorded Plat

5. Private Claims

Property in Sec.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawland/or that the corner points mentioned in lines 3.4 and 5. above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original monument and

sonument.

accessories not found. Found Wisconsin-Michigan Power Co.

LI Original monument and accessories not found.

7 Not set on original murvey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored at MI-MI Power Co.

Restored midway on line.

Established midway on line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Ki NI-MI Power Co. monument. 10" maple 882M 33.7' B2 MBT 6" cherry 876E 7.5' SI NOT 8" charry 859W 16.2' B2 WBT

Li Set 1" 1.3. x 32" 1.7. m/4" aluminum cap. 11" basswood 887W 15.4' 1/49 MOT 14" sugar N&&E 15.6" 1/49 NBT 16" supar 804E 20.1" 1/4s 108T

4" maple SE 4" squared.

Set 1" 3.9. x 32" L.P. m/4" aluminum cap. 13" healock M63E 15.8" 1/168 12" healock \$86W 37.0" 1/168 RT 12" healock \$61E 38.5' 1/168



Signed by Kela

2-26-88

Surveyor's Michigan License No. _

YED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 REYISED MAY 14. 1975