## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

		Iron	COUNTY
		T 42N	R32W
ESCRIPTION OF CORNER _	Section Corner 8, 9, 16, and	17	
ORNER MONUMENT1"	I.D. x 36" iron pipe with 4" a	luminum cap	
ATE MONUMENT PLACED AND	·		
ITNESSES TO CORNER	Aspen 4 N2½°E (mag.) 8.9	ft. "S9, NBT"	
N	Aspen 3 N60°W (mag.) 15.0	ft. "S8, NBT"	
9	1½" I.D. iron pipe N74½°E (	mag.) 33.7 ft.	
	AND		
CIRCLE CORNER REGISTER	ED		
ECCDIDITION IN DETAIL AC	TO HOW CORNER WAS LOCATED AND	IDENTIFIED OR	RESTORED.

Found a 12" I.D. iron pipe N7420E .511 ch. from corner, set by unknown party from unknown evidence. Could find no physical or measurement evidence to support the found pipe as being at the site of the original corner. Nothing found to indicate the likelihood of this much misalignment from surrounding corners in the original survey. Therefore, re-established the corner by single proportionate measurement on line between section corners 1 mile N and 1 mile S, according to the method used in the original government survey. Had double proportionate measurement been used, corner would have fallen 12.5 feet west, rather than to east, as is the found pipe.

SURVEYOR'S SEAL			
DISTRIBUTION:	SIGNED	REGISTERED LAND SUBJEYOR Arthur O. Enger	DATE September 20, 1972
Forestry Division, I	Cansing		
Area Forester	<del> </del>		R 4047
Distant Commerce			Rev. 1/72