PE1_0_1

MAR 0 9 ZCCC

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Requ	irement of Act 14, Mich. 1.A. 1	
For corners in		1	IRON COUNTY
	Located In:	Corner Code #	MICHIGAN
(County)	Located III.	· Comor Court	RECEIVED FOR RECORD
(County)			00 PEG 20 AMIG: 20
1. Public Land Survey	T <u>42N</u> R <u>35W</u>		99 DEC 30 AH 10: 29
	T 42N R 34W	A-9	L. C. Records: L.S. P. 110
	T B		Line & Sair
_	T R	L Company of the Comp	power of hiber
2. Property Controlling S	TR T R		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
in Section S.	TR TR		
3. Miscellaneous S. Property in Sec. S.	T R		Register of Deeds Stamp & File Number
Property in Sec.			
4. Lot No, Recorded Plat			A B C D E F G N I J K L M
			2 5 - 5 - 4 - 3 - 2 - 1 - 1
Section Corner to Sections 24 a	and 25, T42N, R35W		3
Section Corner to Sections 19 and 30, T42N, R34W			4 7 8 - 1 9 10 11 12
		- 40 40 00 44 4	
I, Gary L. Pisoni , in a	a field survey on	Oct. 16 , 19 99 do hereby sta	te 5
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as			6 - 18 - 17 - 16 - 15 - 14 - 13 -
in lines 1 and 2 above were	of survey instructions (of the United States Department of	7
the Interior Bureau of Land Mar	nagement or by a decre	e of a Court of Law and for that the	3 -13
somer points mentioned in lines	s 3, 4 and 5 above we	re in conformance with the rules of	□ • • • • • • • • • • • • • • • • • • •
the Michigan Board of Land St	urvevors or by a Decre	ee of a Court of Law; established	1030- 29282726 - 25-
re-established, monumented, re	covered, found as expr	essed below:	
NOTE: Not more than 2 corners.	all in the same town and	range, may be recorded	32 33 36 36
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
		•	136,
	in 1846 by William A.	and/or subsequent restoration: Burt, U.S. Deputy Surveyor.	PEER GROUP ARPROVED
Original Bearing Tree:		7 lks (4.62 feet)	COUNTY REPRESENTATIVE
	y H. Carleton, U.S. Dep	outy Surveyor made the following r 70 lks (46.20 feet)	new bearing tree:
Sugar B. Description of corner evid	20" \$ 15° E lence found and/or met	hod applied in restoring or reestable	ishing corner:
No evidence of original B.			
The corner position is ma GLO distances North and corner position.	rked by a fence post or South along the Range	orner which runs North and East. line. I accept the fence post corn	The fence corner is consistent with ler as the best available evidence for restoring the
Corner record research or	n file with County Repr	esentative.	
C. Description of monument	for corner and accesso	ries established to perpetuate loca	ting the position of the corner:
At the fence corner set a	5/8" diameter by 30"	long rebar with a 3" diameter alum	ninum cap stamped
as follows: Iron County R established the following	emonumentation, T42N new blazed and scribed	I, R35W, R34W, S-24, S-25, S-19 I bearing trees: (All measurements 13,75 feet	1, 3-30, 1999, 1160 27407 11011 1111011
Ironwood Sugar Maple	7" \$ 71°E 13" \$ 25°W		MICHER OF MICHER
Sugar Maple			an Gline and a state of the sta
Sugar Maple		45,56 feet	W GARY L. The state of the stat
Steel sign po		0.70 feet	PISON TALL
	_		* SURVEYOR
99-110 Signed by Say L	Lane.	Date 12.28-99	No
Signed by	- 7010	Jace	MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, VAN. 28, 1971
Surveyor's Michigan License	No. <u>27457</u>	FORM APPROVED BY	(F) I A III BEVISED MAY 14,1915
			REVISED JAN., 1983 REVISED OCT., 1995