SURVEY & REMONUMENTATION

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JAN 1 3 1998	The second secon	FR RECORDATION Frement of Act 74, Mi		70 MICHIGA	M
For corners in	i	•		RECEIVED FOR	RECORD
Iron SECTION Loc	ated in:	Corner Code #		97 DEC 23 Ph	
1. Public Land Survey T	44N R 32W R R	<u>E-7</u>		Filter of	libie
2. Property Controlling ST in Section ST ST ST ST Property in Sec. ST	R R R R R R		- - - -	Register of Deed	ds Stamp & File Numbe
4. Lot No, Recorded Plat 5. Private Claims			: :	A B C D E	F G H I J K L
Section Corner Common to Sections 16,	17,20,21, T44N	, R32W		2 6 5	3 - 2 - 1
I, Gary L. Pisoni , in a field s that under requirements of P.A. 74, Mic in lines 1 and 2 above were in conforcequired in the current manual of survey the Interior, Bureau of Land Management corner points mentioned in lines 3, 4 and the Michigan Board of Land Surveyors re-established, monumented, recovered,	higan P.A. of 19 rmance with reg instructions of t or by a decree of d 5 above were or by a Decree	170, the corner points in gulations and rules the the United States Depart of a Court of Law and / in conformance with the of a Court of Law; es	mentioned erefore as artment of or that the ne rules of	8 19 20 9 10 30 29	9101112 16151413 21222324 1151413 222324 28 - 272625
NOTE: Not more than 2 corners, all in the son this certificate.	ame town and ran	ige, may be recorded		11	33-34-35-36
A. Description of original monument an	d accessories an	d/or subsequent restor	ation:	13	
Original corner established by Zelotes Original Corner: Cedar Post Original Bearing Trees:		Deputy Surveyor, in Ju	ıly 1849.	!	
On 9/6/84, Keith L. Sackett, RLS with the			4 links (ources, foun		
with a brass cap and located 4" above g S-16, S-20, S-21. DNR Bearing Trees 9/6/84 recorded in La	and Corner Certif	ificate L.5, page 94:			y, 144N, R32W, 5-17,
	Balsam Balsam White Pine	4" N 58° E 5" S 16° W 18" N 74° W	4.2 feet 14.3 feet 40.2 feet		
B. Description of corner evidence foun	d and/or method	applied in restoring or	reestablishir	g corner:	
No evidence of original B.T.s found.					
On 11/7/97, found monument as des Existing Bearing Trees Found:		1	trees by Kei	*	OUR ARROWS
Balsam 6" Balsam 5" White Pine 18"	N 67°E S 16°W N 82°W	4.45 feet 14.46 feet 40.46 feet	:	Mary &	OUP APPROVED (Page 11-11-97
Corner record research on file with C	•	•		Econ COUNTY	REPRESENTATIVE
C. Description of monument for corner	and accessories	established to perpetu	ate locating	the position of the c	orner:
Blazed and scribed the following new Spruce 6" Steel sign post	bearing trees: (S 38°E S 85°E	All measurements take 16.09 feet 0 .97 feet	n to a nail in	side of tree)	ARTE OF MICHICAGE
97-27 Signed by Saug L. Pom	;	•	ber 8, 1997	**************************************	GARY E. PISONI

REPUSED MAY ASSOCIATED LAND