STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

-	Iron	COUNTY
·	T 45 N	R 31 W
DESCRIPTION OF CORNER South 1/16 corner between Sections 3 and 4		
CORNER MONUMENT 1" I. D. x 36" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED September 11, 1970		
WITNESSES TO CORNER Tamarack 14 S55°E (magneti	ic) 18.3 ft.	"1/16S, BT"
(No other trees or suitable	objects near)	1
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

No evidence that the corner had been previously established.

Monument placed on line between section corner 19.988 ch. south and 1/4 corner 19.988 ch. north. Erratic N & S single-wire fence line is 1.12 ch. west.

SURVEYOR'S SEAL

STGNET

Cirthur C. Lugar
GISTERED LAND SURVEYOR

DATE July 26, 1973

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing