

1/25/57

DEAN
LAW
DEN

Fd. NW Cor. Sec. 2 T15
OR NE Cor. Sec. 3 R2E

Fd. 1" iron pipe - sunk
to have been set
BY MISSOURI DEPT. -
CORNER IS NOT MARKED IN
HIGHWAY R/W BOOKLET

N 28° E 8" CHK - 67.50'
N 55° E 10" CHK - 56.45'
N 77° E 15" CHK - 43.00'
9 1/2' N OF FENCE EAST

INGHAM Co.

Sec. 3 | Sec. 2
Jefferson Co.

FILE

See Underwood Map 24-25
T15 R2E