ACKSON COUNTY APPROVED LAND CORNER P.A. 345 of 1999 Chairman	EAST & POST, City of Jackson	SECTION 34	,	. '
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970				
For corners in  JACKSON  (County)		Corner Code ##		
Public Land Survey	T 2 S R 1 W T	I-12		2099418 Page: 1 of 2 12/23/1998 11:248
in Section S  3. Miscellaneous S	R	Mindy Rellly - Jack	son Co. CORREM	L-1589 P-650
4. Lot No, Recorded P	iat		- ABCDEF	GHIJKLM
JEAN R. GUTEKUNST, in a field do hereby certify that under requirements of in lines 1 and 2 above were in conforman current manual of survey instructions of the Management or by a decree of a Court of La above were in conformance with the rules of Court of Law; established, re-established expressed below:	survey on	r 21 , 19 97 O, the corner points mentioned is therefore as required in the of the Interior, Bureau of Land to mentioned in lines 3, 4 and 5 is Surveyors or by a Decree of a	2 6 5 4 3 4 7 8 9 5 6 18 17 16 7 8 19 20 21 9	3 2 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 4 corners, all on this certificate.	in the same town and ran	age, may be recorded	11 31 32 33	34 🕁 35 — 36
A. Description of original monument Original Government Por Beech 28" S 43 1 Ironwood 7" N 21½ Perpetuation by Cook, 1 Willow 10" S 31 1 Continued on back,	st set by Hervey P 38 links (25 E 24 links (15 no date.	arke, Deputy Surveyo .08') .84')		DEAN RUTEKUNST No. 18658
B. Description of corner evidence for Re-established corner taken in 1974.	position from with	esses of Richard E.	Gutekunst, RLS #78	63,
Excavated through 9" or additional evidence of disturbed any old corne	old corner.	Water and sewer lin		
Corner is approximately Accepted 1974 witnesses		<del>-</del>		hant
available evidence of Set a standard Jackson	the position of the	e original corner.	stodivisions as we	198 L
Br: Jac N 25 B Utility Pole N 62 B Top center 1:	mer is a 4" diame ass cap stamped LS ckson County. 58.51' Found ine of fire hydran mer of concrete b	ter X 30" Cast Iron 18658, which is a s i nail and MSHD tag	Harrison monument tandard monument f on Southeast side. 87.12'	with a or
S 40 W Northeast comes 5 53 W Northeast comes 5 55 W Utility Pole N 35 W Utility Pole Monument box set by Mic Signed by	rner of concrete be rner of concrete for 42.24' Found 46.53' Found chigan Department	ase of sign 51.  condation of restaur  1 60d on Worth side.  1 60d on West side.  of Transporation in  Date	01' cant 133.05'	et.
Surveyor's Michigan License No.	18658		IPPROVED BY MICHIGAN STATE COARD OF L	AND SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1989

## Continued,

- Perpetuation by John Holcroft, no date.

Iron bar 1" X 12" at corner, 14" down.

St. John's Church (R.C.) Northwest corner in corner between butrasses 88.35' Southeasterly

Brick house Northeast corner

Southwesterly 59.63

Perpetuation, no name, no date, no description. Southeasterly Northwest corner church 86.5' Northeast corner Brick house Southwesterly

- Perpetuation by Richard E. Gutekunst, RLS #7863, dated March 27, 1974

Set PK nail and cap in blacktop from street corner witnesses and adjacent subdivisions.

Southeast to Northwest corner of concrete corner of Stone church

Northeast to Telephone Fole (MSHD teg) 58.51' Southwest to Northeast corner concrete base sign Northwest to Utility Fole (MSHD tag) 46.61 50.951

87.131

- Information from Timothy B. VanGieson, RIS #24621, dated February 27, 1982.

MSHD 4" Brass disc

59.31 60d in Power Pole N 30 E 51.07 60d in Telephone Pole S-60 E S 55 W 41.82' 60d in Power Pole 60d in Service Pole N 30 W

- Not recorded in P A - 74.

2099418 Page: 2 of 2 12/23/1998 11:24A L-1589 P-650