APPROVED LAND CORNER P.A. 345 of 1990	SOUTHEAST CORNER, SECTION 3 SUMMIT TOWNSHIP	1	
Chairman Sold 3-97 Date 28-13-97	LAND CORNER RECORDATION CERT	IFICATE	#2044419
Porte 28-73-97	Filing Requirement of Act 74, Mich. P.	A. 1970	Liber 1549 Page 139
TACKSON			Page 1 of 2 Jackson Co., MI
(County)	ocated In: Corner Code ##	SURVEY &	Recorded
	T35R1W C-13 REM	NOITATION	08/15/97 10:58A Mindy Reilly
		APR 07 1998	Register of Deeds
t. Property Controlling S	TR	~~~~**********************************	
in Section S	T R	SECTION	
3. Miscellaneous S S Property in Sec. S	T R	Register of Deeds S	Stamp & File Number
	II	A B C D	E F G H I J K · L W
. Private Claims		2	
		3 1 1	
TOAN D CHROMINGS	Ontohom 16 OF	4	-9-10-11-12-
	urvey on October 16 19 95		
	P.A. 74, Michigan P.A. of 1970, the corner points mentic with regulations and rules therefore as required in	the 18 17	-16-15-14-13-
• • • • • • • • • • • • • • • • • • •	United States Department of the Interior, Bureau of Land/or that the corner points mentioned in lines 3, 4 a		
	the Michigan Board of Land Surveyors or by a Decree	o(a	21 22 23 24
· · · · · · · · · · · · · · · · · · ·	, monumented, re-monumented, recovered, found	ا ا امر	
xpressed below:		10 30 29	28 27 26 25
on this certificate.	the same town and range, may be recorded	12 31 32	33343536
		13 1 1 1 1	
-	nd accessories and/or subsequent restoration:		
	t set by Joseph Wampler, Deputy St 28 links (18.48')	urveyor, 1823.	
Y. Oak 14" N 34 W	12½ links (8.25')		
Ferpetuation by H. F. Be	ean, 1886.	Found remains of	both witnesses an
Ferpetuation by H. F. Be * W. Oak 18" N 6 Hickory 20" N	$55\frac{1}{2}$ W $91\frac{1}{2}$ links (60.39') 4 E $51\frac{1}{2}$ links (33.99') stum	set Fireclay pos p 1907 West o	t 42 links (27.72' f Libery post.
Continued on back,			
. Description of corner evidence foun	d and/or method applied in restoring or reestal	blishing corner:	
Found Fireclay, with ire	· -	3	
	center line of Kimmel Road (grave	. 1)	
	areful and faithful perpetuation		f the
	numented by Bean in 1886.	-	THE OF MICHIES
Set a Standard Jackson C	ounty Monument to replace the fir	eclay and buried	oronan de la companya
fireclay around bottom o	f monument.		DEAN
			GUTEKUNST
			No. 18658
			HALLE STORY OF THE STORY
			ENTED LAND STUTE
Description of monument for corner	and accessories established to perpetuate loca	ating the position of the c	corner:
\$	orner is a 4" diameter X 36" conc teel rod and an aluminum cap stam	ped LS 18658, which	n a ½ " X 36 " ch is a
S'	tandard monument for Jackson Coun	ty.	
* N 65° W 30" Oak	60.96' 60d nail on Sou	th side.	,
N 70° E 36" Oak	ry 28.52' 60d nail on Nor 85.70' 60d nail on Sou	theast side.	
S 35° E 20" W. Oal	k 34.25' 60d nail on Wes	t side.	
S 50° W 9" Oak	61.39' 60d nail on Nor	thwest side.	
East Northeast corn	mer of Section 6, Town 4 South, R.		54' (concrete
North Steel post :	and survey marker sagn attached		monument)
gned by	7	August 1, 1997	
rveyor's Michigan License No	3658	ORM APPROVED BY MICHIGAN STATE BOA	RD OF LAND SURVEYORS, JAN. 28, 1971

T3S, RIW

A.) - Perpetuation by Richard E. Gutekunst, RIS #7863, dated March 27, 1972.

Found Fireclay 16" below gravel surface, from one old witness (*).

Large rock on South side, smaller rocks around.

Set a 3/4" X 18" iron beside and on top of fireclay.

*	n 65 w	30" Oak	61.0'
**	N 17 W	21" Hickory	
	N 4 E	17" Oak	60.9'
	N 14 E	28" Oak	28.65'
	N 57 E	5" Hickory	71.4
	S 23 W	4" Hickory	43.3'
	S 19 E	15" Hickory	72.2'

- Not recorded in P. A. - 74.