	JACKSON COUNTY APPROVED LAND CORNER P.A. 345 of 1990 Acting Chairman Con Em	HANOVER TOW → LAND CORNE	ORNER, SECTION 22 INSHIP IR RECORDATION CEI	LIBER RTIFICATE	JACKSON	ACHTEAN I COUNTY IRDED	
Fo	corners in			1	18 NO 85	nere i v	
	JACKSON (County)	ocated In:	Corner Code ##		11 AUG 95	9:46 A.M.	
1.	Public Land Survey	T 4 S R 2 W T R R T R R	G-7			McDEVITT OF DEEDS	
2.	Property Controlling S	T R					
		T R					
3.		T R T R		Register	r of Deeds Stam	p & File Numbe	æ
	Property in Sec. S	1 n	-				
4.	Lot No, Recorded Pl	at	+ 1	A	A B C D E F	в н т ј к	L
5.	Private Claims		·				\Box
				3	ĬĬĬ		
do in I cur Ma abo Co exp	DEAN R. GUTEKUNST, in a field thereby certify that under requirements or ines 1 and 2 above were in conformant rent manual of survey instructions of the nagement or by a decree of a Court of Law ove were in conformance with the rules of urt of Law; established, re-established ressed below: TE: Not more than 4 corners, all in on this certificate.	IP.A. 74, Michigan P.A. ce with regulations and United States Depart wand/or that the corne of the Michigan Board of the monumented, re-namented, re	of 1970, the corner points med rules therefore as require ment of the Interior, Bureau rpoints mentioned in lines 3 f Land Surveyors or by a Denonumented, recovered, for the recovered, for the recovered of the recording the re	ed in the roof Land 7 8, 4 and 5 8 cree of a 9 ound as 10 ed 11 12 13	-19 -17 -16 -19 -20 -21 -30 -29 -28 -31 -32 -33	22 - 23	-2
	Original Government Post Hickory 6" S 53 Hickory 5" S 51 Perpetuation by H. F. Be White Oak 18" N 26 White Oak 22" S 45 Not recorded in P. A. 7	set by Robert E 8 li W 9 li ean, July 1886 E 104 3/ W 104 3/		rveyor, Marc	ch, 1825. one post sta is stone rem		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found large STONE, standing on end, 3' below blacktop surface, with a 2" thick flat stone on the West side. Backhoe excavation of 6' x 6' x 4' deep area to find stone. Stone is 10" x 12" x $2\frac{1}{2}$ " long, and approximately on center line of Folks Road and $3\frac{1}{2}$ " East of center line of Snow Road.

Found a ½" iron in a monument box, to surface of blacktop, 4.15' North of Stone and 4.05'

West of Stone corner. Nothing was found under monument box. See back.

Accepted STONE as a careful and faithful perpetuation of the position of the original corner as remonumented by Bean in 1886. Replaced stone with a Standard Jackson County Monument and left stone on South side of monument and flat stone, set horizontal, on the West side at 3.8' below blacktop.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7	T4S, R2W	steel rod an		36" concrete monument with a $\frac{1}{2}$ " X 36" cap stamped IS 18658, which is the kson County.
n 10° s 70° n 50° s 10°	E	24" Hickory 24" Hickory 30" Oak Double 8" Walnut	144.95' 69.05' 75.05' 173.20'	40d & washer on East side 40d & washer on North side 40d & washer on Southeast side 40d & washer on West side GUTEKUNST
Monume	nt box set	over monument by	Jackson County	y Road Commission. No. 18658
Signed by	ALL,	an Culik se No. 18658	runef	Date December 29, 1994 Confidential Confidence of Land Surveyors, Jan. 28, 1971

B. Continued,

Witnesses to $\frac{1}{2}$ " iron in monument box as witnessed by Dean R. Gutekunst, # 18658, on October, 12, 1989.

N 70° S 60°		30" Hickory 24" Hickory	86.80' 67.96'
S 150	W	24" Oak	78:11'
N 70°	\mathbf{E}	16" Oak	94.691

 $3\frac{1}{2}$ tNorth of center line of blacktop, Folks Road

2'+ West of center line of gravel, Snow Road

í