\$7.00	isin I	22	2000

Surveyor's Michigan License No.

21.33	K	EMI COOMI I KEMI	ONUMENTAT	ION		
\$2.00 SECTIO	)N LAN	D CORNER RECORDA	TION CERTIEIO	· A TI"	<u> </u>	<u> </u>
<b></b>	Fili	ng Requirement of Act	74. Mich. P.A. 19	270	200	30 <u>5</u>
For corners in	•		1			
KENT COUNTY	Located in:	Corner Code #		9,62	1 2 E	779
(County)		Solon Twp.			<b>5</b>	
1. Public Land Survey	T <u>10N</u> R	11W K-12		DEEDS SEEDS	27 mg/m 24 27 mg/m 24 28 mg/m 24	
·	TR		ĺ	0,	<b>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</b>	
	<u>TR</u>				3 5	) ' <del>la</del> s
2. Property Controlling	TR					•
in Section	S TR	<del></del>				
3. Miscellaneous	S TR		1	ના ન	1100	
Property in Sec.	S TR				1106	
			<u> </u>	Register of De	eeds Stamp &	File Number
4. Lot No, Record	ded Plat					4
5. Private Claims				ABCDI	E F G H	ΙJΚι
				2 6 5		
Kirk Breitels				3		
l <sub>a</sub>	in a field survey on	Jan. 14 , 19 99 do her	eby state that under	4 - 7 - 8 -		
conformance with regulations and	rue. Or 1970, the come	er points mentioned in lines 1 a	nd 2 above were in	5		
				6 18 17	16-15-	14 13
that the corner points mentioned in Board of Land Surveyors or by recovered found as expressed ball	a Decree of a Court of	were in conformance with the re f_Law;_established_re-establis	iles of the Michigan	7 1		
recovered, found as expressed belo	OW:	, , , , , , , , , , , , , , , , , , , ,	monamented,	8 19 20	-2122	23 24
NOTE: Not more than 2 come	ers, all in the same tow	n and range, may be recorde	ď	9		
on this certificate.			•	10 30 29		26 25
				11		20 23
				12 -31 - 32	3334	35 36
A Danieller e e e				13		
A. Description of original mon	ument and accessori	es and/or subsequent restor	ation:			
K-12 1837 GLO	Cathcart	Set Post		<b>D. B. C. C.</b> C.		
1966 Kent Co. Wi 1972 LCRC #215		Iron		P.A. 345 1990		
1972 LCRC #213		1 ½" Iron 2" Iron		PEER APPROV		
1981 LCRC #217		Set Kent County Monu	ment	CHAIRMAN /	Larry y	<u>uhu</u>
1990 LCRC #561	8 Marschall	Kent County Monument				
by Robert I. Jonkov.	orner was previously	approved by the Kent Co.	inte Domonius	ation Peer Group, 1	monumented	
by Robert J. Johnsef (	on 10-1-81 and was r	ecorded per LCRC #2179.				
B. Description of corner evide	ence found and/or me	thod applied in restoring or a	reestablishing corne	er.		
N-12 Found Kent County I	Monument (Harrison	) ner witnesses from about	TODO		place of the	
LCRC #2179	and. Said Iron check	es with ixent co. wits, and	LCRC's #215 & #	#279.	brace of the	
	34" Maple N75°W	LCRC #5618	t 400 b.c. 1 5 cc			
Nail & Remon. tag	34" Maple N25°W	54.43' Nail & Remon	tag 40" Maple N7 tag 38" Maple N2	/5°W 33.43'		
Nail & Remon, tag	12" Oak S42°W (	58.50' Nail & Remon.	tag 14" Oak S42	2°W 68.05'		
Nail & Remon. tag Iron West 33.03'	P. Pole S87°E 7	75.13' Nail & Remon.	tag P. P. S8	5°E 75.13'		
C/L B.T. is 1' West	<b>,</b>					
The selected location is	is accepted by me an	d is generally accepted by	professional summer			
<ul> <li>C. Description of monument for K-12 Standard Kent County</li> </ul>	r comer and accesso	ries established to perpetuat	e locating the posit	ion of the corner:	- Militario de Californio de C	MORE TO SERVICE STATE OF THE S
Nail & KC Remon. tag	7 IVIOHUMENT 2 N. side 40" Manla	N75°W 33.43'		يعر العربية	1E OF M	ICH, STA
Nail & KC Remon. tag	g SW side 40" Manle	N25°W 64.05'		A Total	KIRK	N. T. W.
Nail & KC Remon. tag	g E. side 16" Oak	S42°W 68.60'		a the state of the	BREITEL	
Nail & KC Remon. tag	g N. side P. Pole	S85°E 75.13'		* *	LAND	
				* -	SURVEY	OR A
•				tion of the corner:	30077	INV
,				3		AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS
//	IDD				LAND	