

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 57 N.R. 31 W

THAYER LAKE ACCESS

Keweenaw


COUNTY

DESCRIPTION OF CORNER Secs. 32-33, T57N R 31 W
Section Corner common to Secs. 4-5, T56N R31W &

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/3/65 Distances in Feet

WITNESSES TO CORNER..... 1 1/4" Soft Maple (S33 NBT), N 65° E, 17.3'



1 1/2" Y. Birch, (S5 NBT), S 02° W, 31.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner placed at an old blazed Cedar with lines blazed in all four directions.
No Original Evidence at Corner. Found remains of a Pine Line Tree to West.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3/25/1966
REGISTERED LAND SURVEYOR