

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 57 N.R. 31 W

THAYER LAKE ACCESS

Keweenaw


COUNTY

DESCRIPTION OF CORNER Meander Corner betw. Secs. 32-33, on South side of Thayers Lake

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/8/65 Distances in Feet

WITNESSES TO CORNER..... 6" Cedar (NBT), N 50° E, 10.7'



10" Y. Birch (NBT), S 07° E, 26.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner placed on North side of an old blazed Tamarack stub.

Found no original evidence, but Corner does fit calls of notes.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 3/25/1966