

FEB 1 8 1994

1 PG 1076 LIBER

4	-
- /	
2	

COMMISSION LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Act 74, Mich. P.A. 19
DAWIT TON MUD	raing nequirement of ACC 14, Mich. P.A. 13

For corners in PAVILION TWP.

	****		// f
KALAMAZOO «County)	Located In:	Corner Code #	1 5 E
Public Land Survey	T 3S R 10W	B-13	20
·	T R T R		KEGS CE
	<u> </u>		S
2. Property Controlling	SH		
in Section 3. Miscellaneous	S T B		Register of Deeds Stamp
Property in Sec.	S T R	-	negister of Deeds Stamp

. Recorded Plat Lot No.

5. Private Claims _

i, Allen H. McMachema field survey on December 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land. Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1888 - F. Hodgeman C.S. placed Clay Tile post during official Township Remonumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner...

Found Clay Tile 1.7' deep.

RATIFIED " BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 12-30-93



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Harrison Monument and monument box over existing Tile, accessories:

Nail & Tab in West face 30" Oak N. 06 deg. E. 28.55' Nail & Tab in South face 30" Oak N. 60 deg. E. 30.44' Nail & Tab in East 15" Oak S. 37 deg. E. face 33.531 Nail & Tab in East 12" Oak S. 17 deg. E. face 20.71

Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983