SURVEY & **BEMONUMENTATION**

Lot No. __ 5. Private Claims _

APR 2 7 1995

COMMISSION

_ . Recorded Plat _

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN - COUNTY OF KALAMAZOO RECEIVED FOR RECORD

Filing Requirement of Act 74, Mich. P.A. 1970

'94 DEC 15 PM 1 37

For corners in SCHOOLCRAFT TWP.

K!	LAMAZOO (County)	Located In:	Corner Code ##	Jemenjung
1.	Public Land Survey	T4 S R11 W	H-11	CLERK-REGISTER
		T R T R		LIBER 1 PG1231
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

I Allen H. McMachen a field survey on October 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1880'S - F. Hodgeman C.S. Place Clay Tile Post during official Township Remonumentation.

10

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found broken top section of Clay Tile leaning, Dug down and found bottom section of Tile undisturbed.

> RATIFIED BY KALAMAZOO COUNT REMONUMENTATION PEER GROUP



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful & faithful perpetuation of the original corner. Removed broken top section of Clay Tile and placed Harrison Monument over bottom section of Tile. Accessories:

Nai1	٤.	Tab	in	12"	0ak	N.	30°	Ε.	32.79'
Nai1									
Nai1	δ,	Tab	in	36"	0ak	s.	20°	W.	25.321
	_								

Nai1	۶	Tab	in	36"	Oak	s.	20°	W.	25.32
Nail	8.	Tab	in	18"	Oak	N.	35°	W.	29.14

MOTT	Ox	ran	TIL	30.	Uak	Э.	20	14 .	23.34
Nai1	٤.	Tab	in	18"	0ak	N.	35°	W.	29.14

Signed by OO H, Y	NºM	acken
Surveyor's Michigan License No.		6935