APR 28 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED	FOR	RECORI
MEACH FE	1 011	WEGOTH

95 JAN 11 PH 2: 19 LIBER NO. 05 DAGE NO. 013

For corners in Helissa De Vonst Lapeer Located In: Metamora Corner Code ## Twp. REGISTER OF DEEDS LAPEER COUNTY TORIGAN 1. Public Land Survey T 6N_R 10E M-5 R _..... ---- a 2. Property Controlling R in Section S R 3. Miscellaneous S Т R Register of Deeds Stamp & File Number Property in Sec. S т R ... Recorded Plat 5. Private Claims _ . 19 94 Huston K. Kennedy in a field survey on December 31 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as PEER GROU NOTE: Not more than 4 corners, all in the same town and range, may be recorded APPROVEDILAND CONN on this certificate. 12 FER COUNTY A. Description of original monument and accessories and/or subsequent restoration. 1822-GLO Wampler, D.S.; Set Post; 4" Aspen S43*E 38 Links 1.) 1975-Kay, P.S. #14096; Survey L.003, Pg.473 - Fnd 1" Angle Iron (Metamora Twp.)

2.) 1976-Henderson, P.S. #16043; Survey L.003, Fg.800 - Fnd Angle Iron (Dryden Twp.)

3.) 1979-Elrich, P.S. #18986; Survey L.005, Pg.324 - Fnd 1/2" Angle Iron (Metamora Twp.)

4.) 1980-Flrich, P.S. #18986; Survey L.005, Pg.736 - Fnd Iron, used same wit as third Survey (Metamora Twp.)

5.) 1984-Kennedy, P.S. #17623; Unrecorded Survey - Fnd Iron Pipe (Metamora Twp.) RAY DAVIS P.S. CO. SURVEYOR

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd Angle Iron with a P.K. Mail in the centerline of Dryden Road to the Eas & West, which has a bituminous surface, and Thornville Road to the North & South, which has a gravel surface. This corner is als being accepted and being used as a common corner with the Northwest corner of Section 18, and the Southwest corner of Sectio 7, T6N, R11E, Dryden Township.

Witnesses from Recorded Survey \$1, 2 & 3 were used to recover and verify the location of the found Angle Iron with a P.K. Mail

I accept the found angle Iron with a P.K. Mail as the best evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-5 I replaced the found Angle Iron with a P.K. Hail with a 1/2" x 24" Iron Rod w/2" diameter brass cap stamped Lapeer County SE OF MICHIGA

Remonumentation #17623 A-5 & M-5 in a new Monument Box. S32 W 50.48' Set Nail & Remon. Washer NW face Power Pole S49 E 59.20' Set Nail & Remon. Washer NE face Power Pole

N41 E 55.50' Set Nail & Remon. Washer NW face Power Pole N36'W 59.30' Set Nail & Remon. Washer NE face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the position of the original corner.

Signed by 17623 Surveyor's Michig n License No.

January 9, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. REVISED JAM . 1983

HUSTON KENNEDY PROFESSION

17623 PROFESSIONAL

UNEX 3005 PARE 0213