SURVEY & REMONUMENTATION

MAY 2 8 1997

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

96 DEC 27 PH 1: 10

For corners in Malissa Da Vaugh LAPEER Corner Code # Located In: DRYDEN TOWNSHIP 1. Public Land Survey T 6N R 11E M-5 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims in a field survey on MAY certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: 1816 GLO Joseph Wampler Set post No witnesses found 10-31-72 LCRC recorded by Bernard Henderson 16043 in liber 2, page 21 Set PK nail 10-31-72 Survey recorded by Bernard Henderson 16.43 in liber 1, page 761 Set PK nait Survey recorded by Robert Kay 14097 in liber 2, page 683 Found unknown 3-23-74 Survey recorded by Herbert Kobs 14097 in liber 3, page 498 Found PK nail 10-27-75 PEER GROUP Suvey recorded by Charles Getz 25843 in liber 5, page 607 Found unknown Survey recorded by Harold Efrich 18986 in liber 5, page 850 Found PK nail 6. 7-24-79 APPROVED LAND CORNER 7 8-21-80 Survey recorded by Herbert Kobs 14097 in liber 7, page 416 Found PK nail 2-28-86 8. PA 345 OF_1990 9 3-5-87 Survey recorded by Harold Elrich 18986 in liber 7, page 591 Found PK nail APERA COUNTY Survey recorded by Harold Elrich 18986 in liber 7, page 615 Found PK nail 10 8-4-87 3-20-87 Survey recorded by Herbert Kobs 14097 in liber 7, page 695 Found PK nail Survey recorded by Harold Elrich 18986 in liber 7, page 809 Found PK nail 12 1-27-88 SURVEYOR RAY DAVIS ? Survey recorded by Earl Gravlin 23510 in liber 8, page 79 Found PK nail 13 9-23-88 Survey recorded by Donald King 30085 in liber 8, page 532 Found PK nail 14 3-20-89 Survey recorded by Harold Elrich 18986 in liber 8, page 587 Found 1/2" Iron in monument box 15 10-12-89 16 10-12-90 Survey recorded by Harold Elrich 18986 in liber 9, page 234 Found 1/2" Iron in monument box Survey recorded by Earl Gravlin 23510 in liber 9, page 947 Found 1/2" Iron 17 12-9-92 Survey recorded by Donald King 30085 in liber 10, page 182 Found 1/2" Iron in monument box 18 9-18-92 Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" Rebar IN monument box in asphalt apron for Dryden road on centerline Bishop Road. Line up with centerline of Dryden Road to the West No witness found for the corner. 2547.44 feet measured 2547.31 feet Getz L5, P 607; Measured: South to M-6 Dryden Township GLO 40 chs or 2640 feet; North to M-4 Dryden GLO 40 chs or 2640 feet; 2644.92 feet Kobs, King, Elrich and Gravlin; 2644.92 feet measured. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. OF MICHIGAN Placed Lapeer County Remonumentation cap stamped M 5 17635 on found 1/2" rebar AZ 40° 47.19 Set PK with Lapeer County tag in NW face utility pole WILLIAM E AZ 160° 90.501 Set PK with Lapeer County tag in W fsce 24" Willow SODERBERG AZ 260° 159.91 Sst PK with Lapeer County tag in N face utility pole

FORM APPROVED BY MICHIGAN STATE BOARD OF CANCEURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN, 1983

17635

SED LAND SUR

Set PK with Lapeer County tag in NE face utility pole

Date

AZ 320°

Surveyor's Michigan License No

Signed by

50.30