SURVEY & REMONUMENTATION

APR 28 1995

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

94 DEC 19 AHII: 20

LIBER NO. 05 PLOE NO. 164 -Malissa. D. Vaugh REGISTER OF DEOS

`	റ	M	١N	١	SS	ON			
	~		•	•			For	corners	in

For corners in			LAPEER CULLI & HICHIGAN
LAPEER	Located In:	Corner Code ≠	
Countyl	ATTICA TOWNSHIP		
Public Land Survey	T <u>7N</u> A <u>11E</u> T A T A	<u>G-12</u>	
2. Property Controlling	T R S T R		
in Section	S T 🛱		
Miscellaneous	S T B		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No	Recorded Plat		A B C O E F G H I J K L
5. Private Claims			,
	•		
			3
			4 - 7 - 8 - 1 - 9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
HAROLD N. ELRIC	H in a field survey on	JAN 25 . 19 94	5
do haraby cartify that under re	concements of P.A. 74. Michigan P.A. of	1 1970, the corner points memioned	6 18 17-16 5 14 13-
in lines 1 and 2 above were	in conformance with regulations and ructions of the United States Departm	rules the Interior Surgau of Land	7
current manual of survey insti	fa Court of Law and/or that the corner i	points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
shove were in conformance w	uth the rules of the Michigan Board of !	Land Surveyors or by a Decree of a	* 9! <u> </u>
Court of Law: established.	re-established, monumented, re-mo	onumented, recovered, found as	10
expressed below:			10 30 129 10 11 12
NOTE: Not more than 4 of	corners, all in the same town and	I range, may be recorded	
on this certificate			12 31 32 33 4 35 36
			13
A. Description of original	monument and accessories and/	or subsequent restoration:	THE DAME OF A COLD E 37 LINE
1824 L.LYON D.S	. SET 1/2 MILE POST -	IRONWOOD N 51° W 8 L	LINKS, PINE 23" N 66½° E 27 LINK
1871 GILBERT BA	TES IRON STAKE 2' LONG		

1871 GILBERT BATES IRON STAKE 2' LONG

1922 LAPEER COUNTY ROAD PLANS STATION 175+54.5 1/4 CORNER IRON STAKE

DEFL = 0.04' R - INDICATES FENCES EAST & WEST

1974 SWARTZ P.S. LIBER 002, PAGES 529 & 53D 1/2" IRON SET ON LINE BETWEEN SOUTHEAST

CORNER & NORTHEAST CORNER OF SECTION 33 - EAST 31.2 FEET 6" MAPLE, S 60° E 40.6 FEET

24" MAPLE, WEST 22.6 FEET ROAD SIGN

1974 SWARTZ P.S. LIBER 002, PAGE 637 SET 1/2" IRON (SAME TIES AS 1974 LAND CORNER

RECORDATION CERTIFICATE)

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ELRICH P.S. FOUND 1/2" IRON IN PAVEMENT 2639.87 FEET SOUTH CF THE NORTHEAST CORNER OF SECTION 33 AND 2638.89 FEET NORTH OF THE SOUTHEAST CORNER OF SECTION 33 AND ON A STRAIGHT LINE. RECORDED SURVEYS AND LAND CORNER RECORDATION CERTIFICATES ARE USING THIS IRON AS THE EAST 1/4 CORNER OF SECTION 33.

ALSO FOUND 1/2" IRON ROD IN MONUMENT BOX 5.6 FEET NORTH AND 4.1 FEET WEST OF 1/2" IRON RESERVED AS EAST 1/4 CORNER BEING USED AS EAST 1/4 CORNER. LAPEER COUNTY ROAD COMMISSION DUG UP MONUMENT BOX AND 1/2" IRON. UNDER IRON ROD WAS A 1" IRON PIPE APPROXIMATELY 2 FEET LONG. THE 1922 PLANS FOR LAKE PLEASANT ROAD INDICATE AN IRON STAKE FOR THE 1/4 CORNER AND A DEFLECTION.

IT WAS THE OPINION OF THE LAPEER COUNTY REMONUMENTATION PER GROUP THAT THE 1" IRON WAS THE DEST OF STATE OF STA THE BEST LOCATION OF ORIGINAL POSITION OF EAST 1/4 CORNER OF SECTION 33, T7N-R11E, ATTICA THE BEST LOCATION OF ORIGINAL POSITION OF EAST 1/4 CORNER OF SECTION 33, T7N-R11E, ATTICA TOWNSHIP, LAPEER COUNTY, MICHIGAN, AND THAT THE 1/2" IRON ROD SOUTHEAST 7 FEET, MORE OR LESS OF THE 1" PIPE SHOULD BE MONUMENTED AS A CONTROLLING PROPERTY CORNER AND USED AS A REFERENCE

C. Description of monument for Elemer and accessories established to perpetuate locating the position of the corner:

-12	- MONUMENT BOX	PLACED OVER LOCATION OF	EXISTING	1" PIPE,	RESEL 1/2"	THOM OVE	л.
		REMONUMENTATION CAP				PEER GRO	
					A 00 0 C	MED LASH	~ 4

S 70° FAST S 35°	W 69.94 FEET NAIL IN 4" SCOTCH PINE W 57.11 FEET NAIL IN 14" ELM 56.05 FEET NAIL IN POWER POLE E 74.48 FEET NAIL IN COMPONE OF LOCUST
SOUTH	7.02 FEET 1/2" IRON IN MONUMENT BOX (CONROLLING

AND CORNER PA 345 OF 1990 LAPEER COUNTY

3	PROPERTY	FRS CO. SURVEYOR
	OATE	17-19-91

Signed by Harrelon Dila	
Surveyor's Michigan License No18986	TIBER 1005 NEED 1 64 APPROVED BY INICHIBAN STATE BOARD OF LAND SURVEYORS JAN 26 1877 REVISED HAT 14 1975

A. (CONTINUED)

- 1978 KAY P.S. LIBER 004, PAGE 728 1/2" IRON, 1/2" PIPE 5.7 FEET NORTH & 3.9 FEET WEST EAST 31.2 FEET 5" MAPLE STUMP, S 60° E 40.3 FEET 24" MAPLE STUMP, WEST 33.0 FEET 1/2" IRON
- 1978 ELRICH P.S. LIBER 004, PAGE 691 1/2" IRON EAST 31.0 FEET 10" ASH S 60° E 68.4 FEET 20" APPLE, S 30° E 40.08 FEET 24" MAPLE
- 1979 HENDERSON P.S. LIBER OOS, PAGE 320 1/2" IRON (SAME TIES AS
- 1980 HENDERSON P.S. LIBER 005, PAGE 851 1/2" IRON (SAME TIES AS 1978 SURVEY)
- 1983 HENDERSON P.S. LIBER 006, PAGES 519 & 620 FOUND P.K. NAIL N 80° E 52.77 FEET POWER POLE, S 60° E 68.40 FEET 20" STUMP, S 70° W 60.13 FEET 8" CHERRY
- 1988 ELRICH P.S. LIBER 007, PAGE 967 1/2" IRON (SAME TIES AS 1978 SURVEY)
- 1988 FIELD NOTES LAPEER COUNTY FOAD COMMISSION FOUND 1/2" BAR 1.5 FEET UNDER ASPHALT WEST 32.72 FEET 1/2" IRON, EAST 56.04 FEET NAIL IN POWER POLE, N 15° W 123.43 FEET 1" PIPE
- 1993 BAILEY P.S. LIBER 010, PAGE 208 1/2" IRON (SAME TIES AS 1978 SURVEY)
- MOTE: BEGINNING IN 1974 THROUGH 1993, ALL RECORDED REFERENCES TO THE EAST 1/4 CORNER OF SECTION 33 ARE TO THE POINT THAT IS SIX FEET SOUTH AND FOUR FEET EAST OF A 1/2" IRON OVER A 1" PIPE, WHICH WAS DETERMINED TO BE THE BEST LOCATION OF THE ORIGINAL POSITION OF THE EAST 1/4 CORNER OF SECTION 33, 17N-R11E, ATTICA TOWNSHIP, LAPEER COUNTY, MICHIGAN

KISC D 9.00 REMLC POO75 REMONT 2.00

UBERO 0 0 5 PAREO 1 6 5