## SUNVEY & REMONUMENTATION

## APR 2 9 1996 AND CORNER RECORDATION CERTIFICATE

Eiling Requirement of Act 74, Mich	n. P.A. 1970	RECEIVED FOR RECORD  95 DEC 13 AM 8: 50								
For corners in DEERFIELD TWP.  LAPEER Located In: Corner Code #	OGRAM									
(County)		LIBER HO. STATE ST								
1. Public Land Survey		REGISTER OF DEEDS LAPEER COUNTY MICHIGAN								
TR TR	-					•				
2. Property Controlling S T R	-									
3. Miscellaneous S T R Property in Sec. S T R	Registe	gister of Deeds Stamp & File Number								
4. Lot No, Recorded Plat					ABCDEFGHIJKLM					
5. Private Claims	2	6	5	4	3	2	1			
AND THE RESERVE OF THE PARTY OF	<b>3</b> 9 95 , 4						-			
in a field survey on MARCH  19 95  do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a		7	-8	9	10	11	12			
		18	17	16	15	14	13			
above were in conformance with the rules of the Michigan Board of Land Surveyors of by a Decr Court of Law; established, re-established, monumented, re-monumented, recovered, fou expressed below:	nd as 8	19	20	21	22	23	24			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded		30	29	28	27	26	25			
on this certificate.	11 12 13	1 * 1	32	33	34	35	36			
CORNER OF 6 & 7 T9N-R11E; NO OTHER WITS GIVEN  1972 EIRICH, P.S.#18986; LCRC; L.2, PG.9; FND 1/2" IRON; N10W 37.27' 30" ASPEN, S15E 34.62' 8" CAR, S50E 51.69' 20" CAK  1972 HENDERSON-BATES; HENDERSON, P.S.#16043; SURVEY JOB #6196-A; SET 1/2" ROD; SAME WITS AS 1972 LCRC ABOVE; ALSO FND. 1/2" PIPE 12.66' N. AT NW COR. SEC.7 APPROVED LAND CORNER PA 345 OF 1990  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  1994 ROWE ENG.; FIELD, P.S.#37276; FND 1/2" ROD AT C/L EXTENDED OF GRAVEL RD TO W. AND 18'N. OF C/L EXTENDED OF GRAVEL ROAD TO E. ALSO FND 2 WITS GIVEN BY ELRICH IN 1972 INDICATING THAT FND IRON IS IN SAME POSITION  G.L.O. NOTES FOR T9N-R11E INDICATE THAT THIS CORNER IS NOT COMMON WITH A-4 T9N-R11E										
M-3 TO M-2 2609.06' (M.D.O.T.) M-3 TO L-3 2643.14' (HENDERSON 1972) M-3 TO M-4 2636.74' (HENDERSON 1972) 2643.53' (REI 1995)										
2635.75' (REI 1995)  ACCEPTED FND ROD AS A CAREFUL AND FAITHFUL PERPETUATION	OF THE OPEN	TNAT	COBA	ית פק	\@TM*	ONT.				
C. Description of monument for corner and accessories established to perpetuate					,oltt	ON				
M-3 SET STANDARD BRASS CAP ON FND 1/2" ROD  S27°E, 43.56' SET NAIL W/REMON TAG ABOVE FND NAIL  S10°E, 35.00' SET NAIL W/REMON TAG ABOVE FND NAIL  N51°W, 18.51' SET NAIL W/REMON TAG ABOVE FND NAIL  N18°E, 7.40' SET CHIS. + ON LARGE STONE  N43°E, 36.80' SET NAIL W/REMON TAG IN SE FACE 38"  S50°E, 51.90' SET NAIL W/REMON TAG IN NE FACE 24"  S03°E, 12.59' FND 1/2" PIPE  S01°E, 17.82' FND 1/2" ROD	W/FLAG. IN W/FLAG. IN W/FLAG. IN W/FLAG. IN W/FLAG.	NE FA SW FA	CE 14	4" OA 6" OA 4" OA	IK IK INATH INATH LAND	LD	A CONTRACTOR OF THE PARTY OF TH			
Q + m = 1-c0			STATE OF THE PARTY		URIVEY: No. 37276	OR .				

Surveyors Michigan License No. 37276