SURVEY & REMONUMENTATION

APR 28 1995

COMMISSION

1994 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

RECEIVED FOR RECORD

Filing Requirement of Act 74, Mich. P.A. 1970 94 DEC 22 PH 2: 00

> 12 31

32 33 34 35

| For corners in DEERFIELD LAPEER (County) | TWP. Located In: | Corner Code # | | | LISER | 10. <u>0</u> 5 Vielissa | 2_3/4 | : 110 | 176 |
|--|--------------------------|---------------|-------------|------------|-------|----------------------------|------------|-------|-------|
| Public Land Survey | T 09N R 10E T R | | | | P | FOISTE | מים מ | TEBS | \N |
| Property Controlling S in Section S Miscellaneous S Property in Sec. S | T R T R T R T R | | Regist | er of I | Deeds | Stamp | & File | Numb | ier |
| 4. Lot No, Record 5. Private Claims | ded Plat | | - : | <u>A B</u> | СБ | Ęţ | G Н | , , , | (L J |
| | | | - 2 3 | 6 | 5 | 4 | 3 | 2 | 1 |
| JONATHAN M. FIELD | | | , 4 | 7 | 8 | 9 | 10 | 11 | 12 |
| n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land danagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 | | | | 18 | 17 | 16 | 15 | 14 | 13 |
| bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below; | | | 8 | 19 | 20 | 21 | 22 | 23 | 24 |
| OTE: Not more than 4 corn | are all in the same town | and man | 10 | 30 | 29 | 28 | 27 | 26 | 25 |

Description of original monument and accessories and/or subsequent restoration:

1822 GLO; WAMPLER, D.S.; SET POST; IRONWOOD 6 N17W 42LKS., ELM 9 S83W 23LKS.

1906 SICKLESTEEL, C.S.; STAKE; BURR OAK 30 N34 1/2E 57LKS., ELM 22 S31 1/2W 55LKS.

1974 HENDERSON-BATES; ELRICH, P.S.#18986; SURVEY L.2, PG.668; FND 1/2"X 12" BOLT; S30°W 40.03" 12" BOXELDER, N45°E 46.78' 6" BOXELDER, N35°W 57.65' FE POST 1974 ELRICE, P.S.#18986; LCRC L.2, PG.541; FND 1/2"X 12" BOLT; SAME WITS AS 1974 SURVEY ABOVE

1976 HENDERSON-BATES; HENDERSON, P.S.#16043; SURVEY L.3, PG.748; FND 1/2"X 12" BOLT; SAME WITS AS 1974 SURVEY ABOVE

1976 KAY ENG.; KAY, P.S.#14096; SURVEY L.3, PG.982; FND BOLT; SAME WITS AS 1974 SURVEY ABOVE 1977 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.4, PG.144; NO OBJECT STATED; SAME WITS AS 1974 SURVEY ABOVE

1980 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.5, PG.563; NO OBJECT STATED; SAME WITS AS 1974 SURVEY ABOVE

1984 HENDERSON-BATES; ELRICH, P.S.#18986; SURVEY L.6, PG.815; FND IRON SHAFT; S30°W 40.03' 12" BOXELDER, N45°E 46.78' 10" BOXELDER, N35°W 58.30' 6" ELM, EAST 27.64' FE POST

1988 GRAVLIN, F.S.#23510; SURVEY L.7, PG.973; FND IRON SHAFT; SAME WITS AS 1984 SURVEY ABOVE

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ROWE ENG.; FIELD, P.S.#37276; FND 1/2"X 12" BOLT @ APPROX. C/L PI OF GRAVEL RD N-W & ON
LINE W/ FE TO E. GLO NOTES FOR T9N-R11E INDICATE THAT A-7 WAS SET 15 LKS. S. OF M-7 LINE W/ FE TO E. GLO NOTES FOR T9N-R11E INDICATE THAT A-7 WAS SET 15 LKS. S. OF M-7 T9N-R10E HOWEVER THIS CORNER HAS BEEN USED AS COMMON TO BOTH TOWNSHIPS IN SEVERAL, FND NO EVIDENCE OF ANOTHER CORNER; SURVEYS: FND 2 PREVIOUS WITNESSES INDICATING THAT FND HOLT IS IN SAME POSITION AS 1974 HENDERSON-BATES SURVEY

2634,85' M-7 TO M-8 (MEAS, BY OTHERS) 2640.34' M-7 TO M-6 (MEAS. BY OTHERS)

ACCEPTED 1/2" BOLT AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION LAWEER CO. PEER GROUP ACCEPTED 1/2" BOLT AS ALSO BEING A-7 T9N-R10E

C. Description of monument for corner and accessories established to perpetuate locating the position M-7 REMOVED BOLT, SET 1/2" ROD W/ STANDARD BRASS CAP SOUTH, 6.42" W. EDGE OF W. SIGN POST LEG

S33°W, 40.03' FND NAIL W/FLAG. IN SE FACE 18" BASSWOOD N44°E, 46.74' FND NAIL W/FLAG. IN S. FACE 16" BOXELDER

27.69' SET NAIL W/ REMON TAG IN S. FACE FE POST EAST,

S41°E, 34.04° FND NAIL W/FLAG. IN NE FACE FE POST

PEER GROUP APPROVED LAND CORNER

PA 345 OF 1990

on this certificate.

MREEB/CCUTY

LIBER 2005 PLEED 176

JONATHAN

M. FIELD

LAND IRVEYOR

RAY DAVIST S. LO

DATE 12- 22-94