

FEB 1 6 1999

SECTION

Filed under Remonumentation Act 345 of 1990

IBER 1 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 295 STATE OF NICHIGAN LENAWEE COUNTY FILED

For corners in			1ለ ከሮዮ 1000 . በ«ለፎቴርባ ለ¥
Lenawee	Located In:	Corner Code #	10 DEC 1998 9:45:52 AN
(County) 1. Public Land Survey	T <u>- 5-8</u> R <u>- 1- E</u> T R T R	M-10	VICTORIA J. DANIELS REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec 	TR T R		Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H I J K L M
in lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a above were in conformance with	uirements of P.A. 74, Michigan P./ conformance with regulations at tions of the United States Depar Court of Law and/or that the corn the rules of the Michigan Board	A. of 1970, the corner points mentioned not rules therefore as required in the truent of the Interior, Bureau of Land ser points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	4 7 8 9 10 11 12 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 co on this certificate.		n and range, may be recorded	12 31 32 33 34 36 36 36 36 36 36 36 36 36 36 36 36 36
A. Description of original r	nonument and accessories a	ind/or subsequent restoration:	
G.L.O. 1815-16 E 1886 James Blair	Benj Hough set 1/4 Sec. po did survey in Section 30 T	ost W. Oak 24 N 41 W 13 B. 5S R2E and he found stake, c	Oak 12 S 6 W 52 rockery and stones

1963 Kenneth Suydam dug and found large stone, crockery and stake hole on north side of stone. Set 12" X 3/4" iron pipe on top of stone & 1 1/4" X 28" iron pipe in old stake hole 0.33 north of stone. Witness to south iron USGSBM N 79° 15' E 18.98. He also dug for A-10 T5S R2E but only found pieces of crockery. Blairs record called for bricks, dishes, glass, iron & stones. He then set 5/8" steel rod 58.58' (Blairs record) south from the iron on the old stake hole.

1972 Kenneth Suydam "Found iron pipe" and recorded it in L 1 P 213 USGSBM NE 18.79

1972 Werner Sommer found iron pipe as shown on survey recorded in L2 P 184 of surveys USGSBM N 82° E 18.70

1975 Kenneth Suydam "Found PK over iron pipe" and recorded it in L3 P 259 USGSBM N 79º 15' E 18.98

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept. 21, 1998 I dug and found P.K. nail in the original pavement and 1" X 12" galv. pipe under the pavement leaning N.E. Found 1 1/4" iron pipe 2' below the pavement 0.05 W & 0.05 South of the location of the P.K. nail. Set 5/8" X 3' re-rod in the top of the 2' deep found iron pipe and drove them both down. Placed Lenawee County re-mon cap stamped P.S. 13040 on the re-rod and set monument box in newly layed asphalt pavement

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as a careful and faithful perpetuation of the position of the original corner.

USGSBM N 80° E 18.89

Fd. dbl. hd. nail & disc in Elec. pole N 25° E 108.20 Fd. dbl. hd. nail & disc in 9" Quad Walnut S 35° E 40.89

Fd. dbl. hd. nail & disc in 12" Elm S 40° W 60.42

A-10 T5S R2E North 58.54 North

OF MICHIGA GLENN E. RICHARD No. 13040 BOWAL 9

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Sun Chicago Date 9-22-98	
Signed by San E Richard Da	te <i>Nov. 10, 1998</i>	

Surveyor's Michigan License No. <u>13040</u>