## Filed under Remonumentation Act 345 of 1990

LIBER 001 PAGE 91

apr () 1 **199**6

For corners in

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION	Filing	, Requirement	of	Act	74,	Mich.	P.A.	1970
(:-								

<u>Lenawee</u>	Located In:	Corner Code #	
1. Public Land Survey	T <u>- 7 - \$</u> R <u>- 5 - <b>E</b></u> T R T R T R	<u>G-1</u>	NOV 22 1995  LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS
in Section S	T R T R T R	Re	egister of Deeds Stamp & File Number
	TR		A B C D E F G H I J K L M
4. Lot No Record	led Plat		2 6 5 4 3 2 1
5. Private Claims		·	3
,		rey on <u>October 4</u> 19 95_, . of 1970, the corner points mentioned	4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7
in lines 1 and 2 above were in co	onformance with regulations an	d rules therefore as required in the	8 19 20 21 22 23 24
current manual of survey instructio	ns of the United States Depart	ment of the Interior, Bureau of Land	9
above were in conformance with the	he rules of the Michigan Board	er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
NOTE: Not more than 4 corne on this certificate.	ers, all in the same town an	d range, may be recorded	13
A. Description of original me	onument and accessories an	d/or subsequent restoration:	
C1 0 1919 Incenh	Eletcher intersect N Rdv	/ 102 links (67 32) East of post	Set nost at intersection corner


Section 3 & 4 Elm 15 N 13 W 17, Maple 12 N 27 E 18 December 1884, James Blair found a stake 1.02 chain (67.32) East of G-13, T6S-R5E and added tile. May 1977, I set an iron pipe in the pavement 67.32 feet East of G-13, T6S-R5E on line to H-13, T6S-R5E and recorded it in Liber 3, Page 518

Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.

October 4, 1995, The pavement and the monument are both gone. Dug and found one small piece of tile. Set 30" Harrison Monument stamped P.S. 13040 67.32 feet East of G-13, T6S-R5E and on line between G-13 and H-13, T6S-R5E.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

30" Harrison monument stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner. SE. Corner of house foundation N 40° W 334.21 SW. Corner of house foundation N 50° W 94.88



Dbl. hd. nail & disc in 46" Maple S 55° E 29.34 G-13, T6S-R5E, West 67.32  By Peer Group in accordance with P.A. 345  Co. Rep. Alenat Ruhad  Date 10 - 19 - 95.	Dbi. nd. nail & disc in Elec. pole N 25° W Dbi. hd. nail & disc in 46" Maple S 55° E 2 G-13, T6S-R5E, West 67.32
21/4 9 0 1 0	Ratified by Peer Group in accordance with P.A. 345 Signed by Sleve & Ruhard Glenn F. Richard
	Surveyor's Michigan License No. 13040