Filed under Remonumentation Act 345 of 1990

APR 0 1 1996

LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 96

COMMISSION

Ratified by Peer Group in accordance with P.A. 345

Glenn E. Richard

Surveyor's Michigan License No. _13040

Filing Requirement of Act 74, Mich. P.A. 1970

For co	rners in			,						
_Lena	(County)	Located in:	Corner Code #		•	į		es les		AIN.
	, in the second	- 0 0 0 0 1 F							11.	Sle Ain.
1. Pu	blic Land Survey	T <u>-9-\$</u> R <u>-1-E</u> TR	<u>C-1</u>			NOV	22	1995	1'	
		T R				LENA	NEE CO	YTNUC		
2. Pro	operty Controlling S	T R T R				REGIST	TTE D. ER OF	DEEDS	3	
	Section S	Regis	Register of Deeds Stamp & File Number							
_		T R T R								
				1	ABC	DE	FG	нι	J K	LM
4. Lo	t No, Recorded	d Plat		1 2	6	5	4	3	2	
	vate Claims			3		$\dashv +$			++	
	_			4 5	1 1 1	- 8	9	10	11	12
	unn E Dichard	in a field er	urvey on <u>September 25,</u> 19	^		17	6	15	14	-13
do her	eby certify that under requiren	nents of P.A. 74, Michigan P	P.A. of 1970, the corner points me	entioned 7					+	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					19	20	21 -	22	23	24
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						29	28	27	26	25
Court	of Law; established, re-es	stablished, monumented, r	re-monumented, recovered, fo						+	+
•	sed below:			1:		32	33	34	35	36
NOTE	 Not more than 4 corners on this certificate. 	s, all in the same town a	and range, may be recorded	13	3 ———					
	•		11							
Α.	•		and/or subsequent restoration						_	
	W. Oak 10 S 23 E 21 V August 18, 1966, I dug August 24, 1977, W.E. I re-established for C-	V. Oak 36 S 44 W 60 g for this when I was k Frazier & Associates re	ntersect N. Bdy 3.10 chai ooking for C-13-8-1, but fo e-established this corner West of C-13-8-1	ound noth	ning.					ors & b
в.	•		od applied in restoring or ree							
	September 25, 1995, the line between B-1	Found Iron pipe in m 3 and C-13, 8-1 Remov	course of asphalt paveme onument box 0.02 East o red it and set 3/4" X 3' gas nd on the line between E	of the reco spipe cap	ord jog ped G.E	from	C-13-8	-1 and O in th	0.05 ne mo	South of onument
c.	•		es established to perpetuate							
	position of the origjr Dbl. hd. nail & disc in Dbl. hd. nail & disc in	nal corner. n Elec. pole S 40° W 76 n 20" Catalpa S 65° E 9 n stub of pole N 60° E e S 50° E 144.91	91.63	cepted as -	the be			_eethi	開發	CHICA

Co. Repalemed Richard Date 10-19-95

___ Date *Nov. 3, 1995*

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975