Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND (DENTIFIED OR RESTORED.

This corner placed 33.0° South of a Fence Corner, in line with road to South and North of an East - West Road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10/26/67