

May 10, 1965

TO: Frank J. Bray, Surveyor
FROM: Ted M. Rauschel, Forestry Section
SUBJECT: Land Corner Record

Attached is a copy of a land corner record which appears to be in error. The township, range, and description of corner are identical to that of another record received at the same time. However, the notations in the box indicating the corner registered suggest that the corner involved lies between Sections 4-5, T47N, R10W, and 32-33, T48N, R10W, rather than sections 3-4, and 33-34 as stated.

Please examine the attached records, and make corrections or give explanation as appropriate.

DM:vb