

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T.48.. NR.10.W..

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 17, 18, 19, 20

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 5" Tamarack S 23° E 57½ links

5" Black Spruce N 89° W 10½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner as perpetuated by Harold Lawrence, Registered Surveyor.

Two Tamarack stp. bottoms in proper position.

Shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 12, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/13/56  
REGISTERED LAND SURVEYOR