CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner replaced at a scribed wood post, set by H. Lawrence, $\pi.L.S.$

Found remains of a tamarack stump, bearing 138°W 15 links, for a probable bearing tree.

Corner lies $\frac{1}{2}$ chain South of a small lake and in a spruce marsh.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Billy D. Buckler DATE 8-26-70
REGISTERED LAND SURVEYOR