

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 10. W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 17-20 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap -----

WITNESSES TO CORNER .18" Hemlock (1/4S NBT) N 9° W .29 Links -----

.8" White Birch (1/4S NBT) S 45° E .54 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Corner at Intersection of Firelanes E.-W.-S. Found 2" Iron Pipe  
on top of ground, has been removed.

No evidence of original corner.

Shown to us by B. McTiver, District Forester.

Corner placed and witnessed June 3, 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 12/5/58  
REGISTERED LAND SURVEYOR