

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 50.. NR. .8 W. .

--- Luce --- COUNTY

DESCRIPTION OF CORNER Meander Corner for Sections 32-33 on South Shore of  
Bodi Lake

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap -----

WITNESSES TO CORNER 13" White Spruce S5°E 96 Links -----  
Marked "M.C. NBT"

7" Balsam S38°E 100 Links -----  
Marked "M.C. NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced as set by Marcus Schaaf, Reg. Surveyor.

Found Iron Pipe and wood post in place. Found no evidence of original  
B.T.s. Position fits with Meander Corner between 28/33 which is 1.08  
chains North and 3.50 chains East of this Corner.

Corner shown to us by B. McTiver, District Forester.

Corner placed and witnessed March 5, 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler ----- DATE 12/5/58  
REGISTERED LAND SURVEYOR