		ER RECORDATION CERTIFIC	<b>⇒</b> ⇔	C C
For corners in	Filing Requir	ement of Act 74, Mich. P.A.	1970 650	
Livingston (County)	Located In:	Corner Code ##	48843	ET IO 13
Public Land Survey	T <u>2N</u> R <u>3E</u> T R T R	M-12	OHIV, MI	<b>3</b>
In Section S 3. Miscellaneous S	T R T R T R T R		L.S.C.#79m Register of Deeds Sta	mp & File Number
				· · · · · · · · · · · · · · · · · · ·
4. Lot No, Reco. 5. Private Claims			A B C D E	F G H I J K L M
			3	
n Darrell D. Hughes in do hereby certify that under require in lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Couabove were in conformance with the Court of Law; established, re-est expressed below:	ments of P.A. 74, Michigan P.A formance with regulations ar as of the United Stales Depar art of Law and/or that the corn arules of the Michigan Board	. of 1970, the corner points mentione nd rules therefore as required in the rtment of the Interior, Bureau of Lar er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of	ne 7   19   20   19   20   19   20   19   19   19   19   19   19   19   1	-16 -15 -14 -13 - -21 -22 -23 -24 - -28 -27 -26 -25 -
NOTE: Not more than 4 corne on this certificate.	rs, all in the same town a	nd range, may be recorded	11 32 32	-33343536
	N45W 90 1ks.	d/or subsequent restoration:	13 Sept. 13	
white Oak 19	N31E 62 1ks.			<b>199</b> 3
			. الله المنتسم والمنفو	Masion
B. Description of corner evide	nce found and/or method	on on back of sheet: applied in restoring or reestablest of west edge 20 ft		đ
•				
M-12, T2N, R3 pipe, affixed Monumentation faithful reesta 358 DEG. 38.04' 215 DEG. 7.93' 045 DEG. 44.92' 155 DEG. 54.15'	E, IOSCO, repla with 2" dia Corner, P.S.	19834, and is acc e position of the C/S 26" OAK S 15" OAK W/S TWIN 10" CHERR C/S 24" OAK	r with 1-1/4" } stamped "Livi epted as a c original corner	K 36" iron ingston Co. careful and
Dan. 1	4 46	Approved by Liv. Co. I	Peer Group: Nov. 1	7, 1993
aigned by	19834		IRM APPROVED BY MICHIGAN STATE BOAR	RÉVISED MAY 14, 1975
				REVISED JAN., 1983

IOSCO TOWNSHIP, T2N, R3E

M-12, EAST 1/4 CORNER SECTION 36

FIELD 10-26-1993 D.D. HUGHES AND ASSOCIATES, FOWLERVILLE

Found 1/2" iron rod, (no ident. cap) 4' west of west edge 20 ft. wd. gravel road and 26.50' north of found 3/4" iron pipe for west 1/4 corner Sec. 31, Marion Twp. (A-12).

1825, corner first set by Sylvester Sibley, Deputy U.S. Surveyor.

1861, Ezra Fairchilds, subdivides Section 36, shows 1/4 line measures.

1915, Grant Dunning shows falling of 28 links (18.48') with A-12 Marion.

1918, Grant Dunning sets stone 40 chains north of SE cor. Sec. 36, Iosco.

1950, Clay Gordon refers to corner in NE1/4 Sec. 36 survey. Did not say what was found or what was set. No witness'.

1976, Oscar Boss sets 1/2" iron rod on line with NW cor. and West 1/4 corner Sec. 31, Marion. and at fence post hole (26.50' North of West 1/4 cor.) Files Act 74 for this corner (LSC 948) and for A-12 (LSC 950), Marion Twp. showing relationship of corner falling.

1978, Gary Boss uses same corner in NE 1/4 Sec. 36 Survey, L.912, P. 252.

1979, Charles Garlock uses corner in survey, L.968, P.222.

1979, Larry Bryan uses corner in survey, referencing LSC 948.

1980, Gary Boss, uses same corner again, shows falling relationship.

1986, Garlock shows same corner in survey for NE1/4 Sec. 36, Iosco.

1989, Gary Boss shows corner in survey SW1/4 Sec. 31, Marion.

1990, Matthew Brady uses same corner in NE1/4 Sec. 36, Iosco survey.

Surveyors, in recent, have been using same point, as set by Boss in 1976, for corner. Point is tree covered and at West edge gravel road (Dutcher). Measures by different surveyors to M-11 and M-13 agree.