DFC 1 3 1993

1	10	3.10	100	6.0	15	ĸi

For corners in

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Livingston .	Located In:	Corner Code ≠≠		NCY HAISTER (ယ	
Public Land Survey	T2N R 4E	I-13		VILAKI OF DEEI COUNTY	37 · PH	
2. Property Controlling S in Section S. 3. Miscellaneous S: Property in Sec. S.	T R R T R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R R T R R T R R R T R		L.S.C.#47m Register of Dec	eds Stamp 8	සි	ımber
4. Lot No, Record	: led Plat		А В С	DEF	3 H I	JKL
5. Private Claims	1		2 6	- 5 - 4 -	-3-	- }
Darrell D Hughes in a	field survey onOctob	per 22 10 93	4 - 7	-89-	_10	-11-12-
do hereby certify that under requirements in lines 1 and 2 above were in confocurrent manual of survey instructions Management or by a decree of a Court above were in conformance with the r. Court of Law; established, re-estate expressed below:	ents of P.A. 74, Michigan P.A. ormance with regulations and of the United States Departs of Law and/or that the corner ules of the Michigan Board of	of 1970, the corner points mention of rules therefore as required in ment of the Interior, Bureau of La r points mentioned in lines 3, 4 and f Land Surveyors or by a Decree of	the 7 18 19 19 19 19 19 19 19	-1716		-1413
NOTE: Not more than 4 corners on this certificate.	s, all in the same town and	d range, may be recorded	11 12 31	-32 -33-	34	35 36-
A. Description of original monum GLO survey notes: Ap GLO witnesses: Hi BO	ril 15, 1825	or subsequent restoration:			•	
•						
Additional historical B. Description of corner evidence Search of the area four and a measurement by Momeasured East 2647.26! dia. at approx bearing Schafer Road. said poin North 24.75! to the factorically Oldov't lines. Then mea 1880 measure of 2647.2	e found and/or method and nothing and no iles W Bullock, Co to the S ¼ cor. S of N48E (true) and tined very good ce of an Old corned Roadside fences sured East 2646.19	pplied in restoring or reestab known surveys tied to sec. 35 T2N-R4E. Found dec. 35 T2N-R4E. Found dec. 36' to livith an existing OL er post of fence line in Livingston County of to S % cor. Sec. 3	to said corner 4½E56 ch. (2 md remains of a point on e. D fence line a North and row were built 15 and compare	36.96')-Wastump xisting control to the No adside fe rods No d with Bu	NO 4 a about center orth, ence t orth o ullock	nd 18" line of meas'd. o the f 's
C. Description of monument for a I-13: SW cor. Section on top and in a North-24.75'-fac N50E-36.96'-ctr North-109.72'-sp S45E-57.83'-sp S20E-90.60'-sp North	MOn. Box. ce of OLD wood cor . OLD stump (Bullo o W/s 12" Cedar N/s 8" Walnut	. post and fence lin		the corner: Liv. Co.	brass	сар

59HILTON

No.

Signed by _

S10W-66.02'-sp W/s 16" Cedar and on ctr. of Schafer Rd.

Į.

OF Approved by Liv.Co. Peer Group: Oct. 30, 1993

October 23, 1993

I-13: SW Cor. Sec. 35 Marion Twp. Liv. Co. MI

I did sweep of the area and did not find any irons except an iron for NW Cor. Sec. 2 Putnam Twp. Found very old fence line to the North and a road side fence line at about half the distance of typical Livingston Co. old R.O.W. fences. Also found an 18" stump about N54°E. Therefore by measuring 24.75' (½ of a 3 rod distance) Southerly from face of post and 36.96' (.56 ch.) from center of 18" stump I found they intersected at a point in line with old fence line to the North and also fell on the existing center line of Schafer Rd. Then measuring East to the S 1/4 Sec. 35 I found the distance to be 2646.19'; Bullock had measured 2647.26' in 1880. Set a temporary PK spike for SW Cor. Sec. 35 which I feel is the correct location based on the above facts and findings. Found no surveys in the area due to large tract ownership. NW Cor. Sec. 2 Putnam Twp. is located 31.00' East and 3.11' South of a line between SW and S 1/4 Cor. Sec. 35. Road surface is asphalt with trees located to the West, Southerly to ESE, open to the North.